HILLER ROAD REALIGNMENT

Final Corridor Feasibility Study Project Number: 08-RSOQ TR 0003

Prepared for:

City of Maricopa
Public Works Department
45145 West Madison Avenue
Maricopa, Arizona 85239

Prepared by:



4561 East McDowell Road Phoenix, Arizona 85008 [602] 454-0402 Tel [602] 454-0403 FAX

June 2008

COM PN: 08-RSOQ TR 0003

APN: AZE0721




TABLE OF CONTENTS

EXECUTIVE SUMMARY	iii
1.0 INTRODUCTION	
1.2 Problem Statement	1
1.3 Study Purpose	4
2.0 EXISTING CONDITIONS2.1 Roadway Characteristics	
2.2 Land Use	
2.3 Traffic	
2.4 Utilities	
2.5 Drainage	7
2.6 Right-of-Way	8
3.0 FUTURE CONDITIONS	10
3.2 Traffic	10
3.3 Design Criteria	10
4.0 ALTERNATIVE CONCEPTS	
4.2 Alternative 2 - Hiller Road-Green Road-Smith-Enke Road Alignment	13
4.3 Alternative 3 – Hiller Road-State Land-Smith-Enke Road Alignment	15
5.0 EVALUATION OF ALTERNATIVES 5.1 Evaluation Criteria 5.2 Evaluation Matrix 33464 CHRIS C.	
6.0 RECOMMENDATIONS FOR FURTHER STUDY	20 1/11



LIST OF FIGURES

Figure 1 Project Location	2
Figure 2 Corridor/Study Area	
Figure 3 Typical Street Sections	12
Figure 4 Proposed Alternatives	14
LIST OF TABLES	
TABLE 1 Existing Right-of-Way Widths	
TABLE 2 Alternative Evaluation Matrix	19
LIST OF APPENDICES	
APPENDIX A: Survey Report	A
APPENDIX B: Alternative 3 Conceptual Plans	





EXECUTIVE SUMMARY

This report presents the initial alternatives developed for the Hiller Road Realignment Corridor Feasibility Study from Warren Road to White & Parker Road located in the northern City Limits of the City of Maricopa.

The purpose of the Hiller Road Realignment Corridor Feasibility Study is intended to determine the financial, environmental and cultural feasibility of the planning or possible construction of Hiller Road. The study results will provide the City of Maricopa with information to help it determine whether the idea should be advanced for further study and consideration.

Three alternatives and a No-Build alternative were evaluated as part of this study. The alternatives were judged based on the following criteria: right-of-way requirements, transportation/drainage infrastructure, utility impacts, potential environmental considerations, and preliminary project cost.

In summary, Alternative 3 was recommended for further study. Alternative 3 is comprised of 3 segments known as A,B,&C. Segment A begins at Warren Road and runs Easterly along the City of Maricopa northern city limits to Green Road. The proposed typical street section will follow the City of Maricopa's Minor Arterial Street Section within this segment. The proposed typical street section will consist of 2 lanes in each direction separated by a 14-foot wide raised median located within a 110-foot wide right-of-way corridor. This proposed typical street section would be located entirely within the City of Maricopa and does not require any right-of-way from the Gila River Indian Community.

Segment B begins at the intersection of Hiller Road/Green Road and continues diagonally from the northwest to the southeast across a State Land parcel to Mobile Road. The proposed typical street section will follow the City of Maricopa's Principal 2 Arterial Street Section within this segment and will consist of 3 lanes in each direction



separated by a 20-foot wide raised median located within a 150-foot wide right-of-way corridor.

Segment C extends along Mobile Road through the John Wayne Parkway and continues east along Smith-Enke Road to White & Parker Road. The proposed typical street section within these segments will follow the Principal 2 Arterial Street Section (Modified) and will consist of 3 lanes in each direction separated by a 14-foot wide raised median located within a 110-foot wide right-of-way corridor. A modified typical street section is required within this segment of the proposed alignment in order to minimize the impact to existing residential properties located along Smith-Enke Road.

This alternative would construct a new 5 lane bridge crossing over the Vekol Wash and require the widening of the existing bridge along Smith-Enke Road over the Santa Cruz Wash to accommodate one additional lane in each direction.

The following are major issues/factors that contribute to the decision to recommend Alternative 3:

- Alternative 3 proposes to design the Hiller Road Realignment so that it is continuous and does not require a reduction in design speed in order to accommodate a left turn or right turn movement for vehicles that travel between Mobile Road/Smith-Enke Road and Hiller Road.
- This alternative proposes an alignment that divides the State Land property east
 of Green Road. The proposed roadway alignment would create a potential
 development corridor along the Hiller Road Realignment that would increase the
 economic potential for the City of Maricopa.
- Minimal impact to residential/commercial properties is anticipated with this alternative.
- This alternative would widen the existing Smith-Enke Road bridge over the Santa
 Cruz Wash instead of constructing a entirely new bridge along the Hiller Road



alignment. A new bridge along the Hiller Road alignment would increase project costs significantly and require more impact to "Waters of the US".

Although Alternative 3 was recommended for further study, Alternative 1 may be a viable alternative for future consideration if the Gila River Indian Community wants to be a willing partner with the City of Maricopa in the ownership and construction of this alternative. The City of Maricopa does not have any jurisdiction to obtain right-of-way from the Gila River Indian Community; therefore, Alternative 1 was evaluated entirely outside of the Gila River Community boundary.



1.0 INTRODUCTION

1.1 Corridor Description

This report presents the initial alternatives developed for the Hiller Road Realignment Corridor Feasibility Study from Warren Road to White & Parker Road located in the northern City Limits of the City of Maricopa as shown in **Figure 1**, *Project Location*. The entire corridor lies within Pinal County and is bordered by the Gila River Indian Community (GRIC) to the north. The following existing roadways are located within the corridor study limits:

- · Hiller Road from Warren Road to White & Parker Road
- Green Road from Hiller Road to Mobile Road (State Route (SR) 238)
- Mobile Road (SR 238) from Green Road to the John Wayne Parkway (SR 347)
- Smith-Enke Road from the John Wayne Parkway (SR 347) to White & Parker Road

The corridor study area is shown in **Figure 2**, *Corridor/Study Area*. The total length of the initial alternatives developed for the Hiller Road Realignment Corridor measures between 8 to 9-miles depending on the alternative.

1.2 Problem Statement

Since incorporation in 2003, the City of Maricopa has developed a grid system of streets and roads that attempt to facilitate an efficient, safe, transportation system for residents and employees. However, as the City of Maricopa experiences hyper growth, issues have arisen regarding roadway capacity, deterioration of existing infrastructure, and connectivity with existing and future development.

The City of Maricopa, located between two Native American Communities (Gila River Indian Community and Ak-Chin Indian Community), has one primary north/south connection to the Phoenix metropolitan area, SR 347. The City of Maricopa is working to provide residents of Maricopa with alternative intraregional and interregional routes to compliment SR 347 and






Figure 1 Project Location






Figure 2 Corridor/Study Area



to develop a series of high capacity loops for Maricopa. The loop systems are needed to accommodate both the residential and business related traffic.

City of Maricopa officials are well aware of the need for the City of Maricopa, Arizona Department of Transportation (ADOT) and other jurisdictions to support families currently living within the City and those to come. During the City of Maricopa's Special Census in 2005, records show that population was at 15,934 and current estimates show that there are over 33,000 living within the City Limits. With continually increasing vehicle trips, alternative routes are necessary and would alleviate the traffic congestion on the principal arterial streets within the City of Maricopa.

1.3 Study Purpose

The purpose of the Hiller Road Realignment Corridor Feasibility Study is intended to determine the financial, environmental and cultural feasibility of the planning or possible construction of Hiller Road, a potential corridor at the most northern boundary of the City of Maricopa. The study results will provide the City of Maricopa with information to help it determine whether the idea should be advanced for further study and consideration.



2.0 EXISTING CONDITIONS

2.1 Roadway Characteristics

The existing roadways within the study area vary from unpaved farm roads to 4-lane paved arterial roadways. Along the Hiller Road alignment corridor from Warren Road to White & Parker Road, there are no existing paved roadways. Instead, there are existing unpaved roads that provide access for the property owners and farmers located along the Hiller Road alignment. These existing unpaved roads are not continuous throughout the corridor study area and in most cases are located within the boundary of the Gila River Indian Community.

Green Road consists of an unpaved roadway from Mobile Road north and becomes an existing residential driveway just over a ½-mile north of Mobile Road.

Mobile Road (SR 238) between Green Road and the John Wayne Parkway (SR 347) is predominantly a two-lane paved roadway located within ADOT's Right-of-Way and jurisdiction. As Mobile Road approaches the John Wayne Parkway it widens out to a 5-lane section to accommodate the turning movements and developments located along the corridor. Posted speed limits along Mobile Road range from 45 to 55 mile per hour.

Smith-Enke Road between the John Wayne Parkway (SR 347) and White & Parker Road is classified as a Minor Arterial and primarily consists of a 4-lane roadway section with a raised median, curb & gutter, sidewalk, street lighting and full landscaping. There are a few segments of Smith-Enke Road where development has not yet occurred and the roadway consists of the original 2-lane roadway section without curb and gutter. Posted speed limits along Smith-Enke Road range from 35 to 45 mile per hour.

Traffic at intersections is primarily controlled by STOP signs on the minor approaches. The intersection of Smith-Enke Road/Porter Road is controlled by three-way STOP signs. The intersection of Smith-Enke Road/White & Parker Road is controlled by a STOP sign in



the eastbound direction. The only existing signalized intersection located within the study area is at the Mobile Road/Smith-Enke Road and John Wayne Parkway intersection.

There is an existing bridge along Smith-Enke Road over the Santa Cruz Wash just less than 1-mile east of the John Wayne Parkway.

2.2 Land Use

The current land use varies along the corridor study area. North of the Hiller Road alignment corridor is entirely within Gila River Indian Community land and is primarily native desert with the exception of a 1-mile segment from Porter Road to White & Parker Road that is being used for agricultural purposes. The south half of Hiller Road between Warren Road to approximately ½-mile west of John Wayne Parkway is located in a rural area that also includes agricultural land, a golf course and State Land property. The south half of Hiller Road from ½-mile west of John Wayne Parkway to White & Parker Road is primarily residential communities with some commercial properties.

Along west side of Green Road from Hiller Road south to Mobile Road the current land use is a rural area that includes agricultural land and the primary residence for the property owner. The east half of Green Road is native desert located within State Land.

The first half mile of Mobile Road east of Green Road is native desert land with the north half located on State Land and the south half on privately owned property. The next half mile of Mobile Road to the east is located on State Land that is currently used for agricultural purposes. The remaining north half of Mobile Road to the John Wayne Parkway is a combination of residential and commercial properties. The south half of Mobile Road from a half mile east of Green Road to the John Wayne Parkway is primarily residential communities with some commercial properties located near John Wayne Parkway.



Large master planned residential communities are located along most of the north and south sides of Smith-Enke Road from John Wayne Parkway to White & Parker Road. Commercial properties are proposed in the northwest corner of the intersection of Smith-Enke Road and Porter Road.

2.3 Traffic

Existing traffic conditions in the study corridor are documented in the *Regional Transportation Plan Update* prepared by Wilson & Company. There are no existing average daily traffic (ADT) volumes along Hiller Road or Green Road within the study area. Existing ADT volumes are 10,300 vpd on Mobile Road and 16,400 vpd on Smith-Enke Road. Current capacity on Mobile Road and Smith-Enke Road are adequate to accommodate existing peak hour traffic volumes at a level of service of "C" or better.

2.4 Utilities

The existing utilities within the corridor include the San Carlos Irrigation District, Global Water, Arizona Public Service, Broadwing Communications, El Paso Natural Gas, Electrical District No. 3, Kinder Morgan Energy, Maricopa Broadband, Orbital Communications, Qwest and Southwest Gas.

2.5 Drainage

The general off-site flow pattern is from north to south over the entire study limits. There are two main washes that run across the project study limits. Vekol Wash is located between the White Road and the Green Road alignments. Santa Cruz Wash is located along the Smith Road alignment. There is an existing bridge along Smith-Enke Road that conveys flows from the Santa Cruz Wash.

Flood insurance Rate Maps (FIRM) have been prepared and published by the Federal Emergency Management Agency (FEMA) for the study corridor limits. Current FIRMS, in general, delineate the land within the project corridor to be one of the following designations:



- Zone D Areas in which flood hazards are undetermined, but possible.
- Zone X Areas determined to be outside the 0.2% annual chance flood.
- Zone A No base flood elevations determined.
- Zone AO Flood depths of 1' to 3' (usually sheet flow on sloping terrain); average depths determined, for areas of alluvial fan flooding, velocities also determined.

2.6 Right-of-Way

The existing right-of-way throughout the corridor varies from a minimum of 66-feet to a maximum of 130-feet. The general right-of-way widths are tabulated below in Table 1, *Existing Right-of-Way Widths*.

	TABLE 1	
	Existing Right-of-Way Widths	
Roadway	Location	Right-of-Way Width
Hiller Road	Warren Road to White & Parker Road	33' (South of GRIC)
Green Road	Hiller Road to Mobile Road	66'
Mobile Road	Green Road to John Wayne Parkway	Varies 66' to 100'
Smith-Enke Road	John Wayne Parkway to White & Parker Road	Varies 83' to 130'

A survey report was prepared to detail the history and true position of the South Boundary of the GRIC boundary in Township 4 South, Range 2 East, and Township 4 South, Range 3 East, of Gila and Salt River Meridian, within the City of Maricopa, Arizona. The location of this boundary has been the source of uncertainty in the past several years, resulting in the perception that a strip of "no-man's land", up to several hundred feet wide, exists along the common boundary between the City of Maricopa and the Gila River Indian Community. The intent of the report is to clarify the record title associated with this strip of land.

The complete report is included in **Appendix A – Survey Report**. In summary, the gap of "no-man's land" between the South Boundary of Sections 7 through 12, and the South boundary of the Gila River Indian Community were determined by the Bureau of Land Management (BLM) to belong to the Gila River Indian Community. The City of Maricopa



was informed recently by one of the property owners along the route that a lawsuit is ongoing regarding the location of the Gila River Indian Community Boundary. This study contacted the Arizona Attorney General's Office and there were not any pending lawsuits that were related to the "no-man's land". Should there be an on-going case, the resulting court decision could have an impact on the location of the Gila River Indian Community boundary.



3.0 FUTURE CONDITIONS

3.1 Land Use

The City of Maricopa anticipates a significant amount of growth in residential, commercial and industrial developments throughout the corridor. The City of Maricopa has recently annexed a large 14-square mile area adjacent to the west end of the project study area.

3.2 Traffic

Traffic conditions have been estimated for the design year 2030. If no improvements are made to the roadway infrastructure within the project area, the level of service is predicted to decline to "F" by year 2030 for Mobile Road and Smith-Enke Road.

3.3 Design Criteria

Design criteria for the proposed roadway improvements anticipated for the project study corridor shall follow the *Regional Transportation Plan Update (2008) – Recommended Roadway Design Standards.* The following design criteria from the *Regional Transportation Plan Update* are recommended to assure compliance with the City of Maricopa requirements:

1) Minor Arterial

a)	Design Speed	45 to 55-miles per hour
b)	Posted Speed	40 to 45-miles per hour
c)	Right-of-Way Width	110-feet
d)	Number of Lanes	4
e)	Street Width (to back of curb)	75-feet
f)	Pavement Width	2 X 28.5-feet
g)	Lane Width	12-feet
h)	Median Width/Left Turn Lane	14-feet (curbed)
i)	Pedestrian Facilities	6-feet detached w/ 5-feet buffer
j)	Bike Facilities	6-feet (includes 1.5-feet gutter)
k)	Driveway Access	Major Driveways Only – 1/4-mile Spacing



Limit Left-Out to 1/4-mile Locations

2) Principal 2 Arterial

a) Design Speed 45 to 55-miles per hour b) Posted Speed 40 to 45-miles per hour c) Right-of-Way Width 150-feet d) Number of Lanes 6 e) Street Width (to back of curb) 109-feet f) Pavement Width 2 X 42.5-feet g) Lane Width 12 to 14-feet h) Median Width/Left Turn Lane 20-feet (curbed) Pedestrian Facilities 6-feet detached w/ 5-feet buffer Bike Facilities 6-feet (includes 1.5-feet gutter)


3) Principal Arterial 2 (Modified)


k) Driveway Access

a)	Design Speed	45 to 55-miles per hour
b)	Posted Speed	40 to 45-miles per hour
c)	Right-of-Way Width	110-feet
d)	Number of Lanes	6
e)	Street Width (to back of curb)	97-feet
f)	Pavement Width	2 X 39.5-feet
g)	Lane Width	11 to 12-feet
h)	Median Width/Left Turn Lane	14-feet (curbed)
i)	Pedestrian Facilities	6-feet attached to back of curb
j)	Bike Facilities	6-feet (includes 1.5-feet gutter)
k)	Driveway Access	Limit Left-Out to 1/4-mile Locations

The proposed typical street sections under consideration as part of this study are shown on **Figure 3**, *Typical Street Sections*.










Figure 3 Typical Street Sections



4.0 ALTERNATIVE CONCEPTS

The following alternatives were developed and evaluated as part of this study:

- Alternative 1 Hiller Road Alignment
- Alternative 2 Hiller Road Green Road Smith-Enke Road Alignment
- Alternative 3 Hiller Road State Land Smith-Enke Road Alignment
- No Build Alternative

Each alternative is depicted on **Figure 4**, **Proposed Alternatives**.

4.1 Alternative 1 – Hiller Road Alignment

Alternative 1 begins at Warren Road and runs entirely along the proposed Hiller Road alignment at the City of Maricopa northern city limits to White & Parker Road. The proposed typical street section will follow the City of Maricopa's Minor Arterial Street Section for the entire project limits. The proposed typical street section will consist of 2 lanes in each direction separated by a 14-foot wide raised median located within a 110-foot wide right-of-way corridor. This proposed typical street section would be located entirely within the City of Maricopa and does not require any right-of-way from the Gila River Indian Community. However, this alternative would significantly impact the existing residences located along the recently constructed developments located along the northern city limits. This alternative would construct a new 5 lane bridge crossing over the Vekol Wash and a new 7 lane bridge crossing over the Santa Cruz Wash.

4.2 Alternative 2 – Hiller Road-Green Road-Smith-Enke Road Alignment

Alternative 2 begins at Warren Road and runs along the proposed Hiller Road alignment at the City of Maricopa northern city limits to Green Road. The proposed typical street section will follow the City of Maricopa's Minor Arterial Street Section within this segment. The proposed typical street section will consist of 2 lanes in each direction separated by a 14-foot wide raised median located within a 110-foot wide right-of-way corridor. This proposed typical street section would be located entirely within the City of Maricopa and does not require any right-of-way from the Gila River Indian Community.






Figure 4 Proposed Alternatives



From the Hiller Road/Green Road intersection, the proposed alignment heads south along the Green Road alignment to Mobile Road. The proposed alignment continues along Mobile Road from Green Road to a mile east. The proposed typical street section will follow the City of Maricopa's Principal 2 Arterial Street Section within these segments and will consist of 3 lanes in each direction separated by a 20-foot wide raised median located within a 150-foot wide right-of-way corridor. This segment of the proposed alignment may impact an existing residence located along Green Road.

Alternative 2 extends along Mobile Road through the John Wayne Parkway and continues east along Smith-Enke Road to White & Parker Road. The proposed typical street section within these segments will follow the Principal 2 Arterial Street Section (Modified) and will consist of 3 lanes in each direction separated by a 14-foot wide raised median located within a 110-foot wide right-of-way corridor. A modified typical street section is required within this segment of the proposed alignment in order to minimize the impact to existing residential properties located along Smith-Enke Road.

This alternative would construct a new 5 lane bridge crossing over the Vekol Wash and require the widening of the existing bridge along Smith-Enke Road over the Santa Cruz Wash to accommodate an additional lane in each direction.

4.3 Alternative 3 – Hiller Road-State Land-Smith-Enke Road Alignment

Alternative 3 is comprised of 3 segments known as A,B,&C. Segment A begins at Warren Road and runs easterly along the City of Maricopa northern city limits to Green Road. The proposed typical street section will follow the City of Maricopa's Minor Arterial Street Section within this segment. The proposed typical street section will consist of 2 lanes in each direction separated by a 14-foot wide raised median located within a 110-foot wide right-of-way corridor. This proposed typical street section would be located entirely within the City of Maricopa and does not require any right-of-way from the Gila River Indian Community.



Segment B begins at the intersection of Hiller Road/Green Road, and continues diagonally from the northwest to the southeast across a State Land parcel to Mobile Road. The proposed typical street section will follow the City of Maricopa's Principal 2 Arterial Street Section within this segment and will consist of 3 lanes in each direction separated by a 20-foot wide raised median located within a 150-foot wide right-of-way corridor.

Segment C extends along Mobile Road through the John Wayne Parkway and continues east along Smith-Enke Road to White & Parker Road. The proposed typical street section within these segments will follow the Principal 2 Arterial Street Section (Modified) and will consist of 3 lanes in each direction separated by a 14-foot wide raised median located within a 110-foot wide right-of-way corridor. A modified typical street section is required within this segment of the proposed alignment in order to minimize the impact to existing residential properties located along Smith-Enke Road.

This alternative would construct a new 5 lane bridge crossing over the Vekol Wash and require the widening of the existing bridge along Smith-Enke Road over the Santa Cruz Wash to accommodate one additional lane in each direction.



5.0 EVALUATION OF ALTERNATIVES

5.1 Evaluation Criteria

Five criteria have been employed to evaluate the potential impacts of the proposed Hiller Road Realignment corridor alternatives. Each evaluation criterion is briefly described below.

- Right-of-Way Requirements This criterion evaluates each alternative based upon the amount of right-of-way required. Right-of-way needs have been tentatively estimated based upon the amount of right-of-way required for roadway construction. At this stage in the study, no additional width has been assumed for future utilities or drainage easements.
- Transportation/Drainage Infrastructure This criterion identifies any major transportation/drainage infrastructure improvements required as part of any alternative. Infrastructure improvements include bridges and/or culverts.
- Utility Impacts This criterion evaluates each alternative on the basis of major utility relocations. The relocation of any utility entails an additional cost to the City of Maricopa (if the utility has Prior Rights) or the utility company (if no Prior Rights exist).
- Potential Environmental Considerations This criterion considers the
 preliminary social and economic considerations; amount of disturbance to
 developed areas and vegetation; and impacts to private property. The need for
 federal regulatory permits is also included.
- Preliminary Project Cost This criterion rates each alternative based on preliminary project cost. Costs of the alternatives have been determined using rough estimates consistent with the level of study to date.

5.2 Evaluation Matrix

Table 2 – Alternative Evaluation Matrix is a matrix of preliminary evaluations of alternatives considered as part of this study. The matrix is not intended to evaluate alternatives against the "No Build", but only to compare them with each other, since the



"No Build" will be carried through the process regardless of the outcome of this preliminary evaluation. Each cell contains a description of the potential advantages and drawbacks of an alternative with respect to a specific criterion.



Bridge New culvert crossings Impacts to Existing Gas Regulators Aguators A	Table 2							
Stracres of new right-of-way required			Alternative Evalua	ation	Matrix			
Transportation/Drainage Infrastructure ***	Evaluation Criteria	ernative 1	Alte	Alternative 3				
required New culvert crossings			of-way required		way required		of-way required	
Gas Regulators Regulators May Impact Existing Water Wells Impacts to 12kV Overhead Power & Cabinets Potential Environmental Concerns Major impact to several existing residential homes Impacts to agricultural property Impacts to existing golf course Potential cultural resources in the area At least one location where impacts to Water Wells Impacts to 12kV Overhead Power & Cabinets Impact to one residential home property Impacts to agricultural property Potential cultural resources in the area At least one location Waters of the US Waters of the US Impact to State Land Regulators May Impact Existing Water Wells Impacts to 12kV Overhead Power & Cabinets Impacts to one residential home property Impacts to agricultural property Impacts to existing golf course Potential cultural resources in the area At least one location Waters of the US occur State Land		*	required		Widen existing Smith- Enke/Santa Cruz Wash Bridge		Widen existing Smith- Enke/Santa Cruz Wash	
Gas Regulators Regulators May Impact Existing Water Wells Impacts to 12kV Overhead Power & Cabinets Potential Environmental Concerns Major impact to several existing residential homes Impacts to agricultural property Impacts to existing golf course Potential cultural resources in the area At least one location where impacts to Water Wells Impacts to 12kV Overhead Power & Cabinets Impact to one residential home property Impacts to agricultural property Potential cultural resources in the area At least one location Waters of the US Waters of the US Impact to State Land Regulators May Impact Existing Water Wells Impacts to 12kV Overhead Power & Cabinets Impacts to one residential home property Impacts to agricultural property Impacts to existing golf course Potential cultural resources in the area At least one location Waters of the US occur State Land								
* May Impact Existing Water Wells * Impacts to 12kV Overhead Power & Cabinets Potential Environmental Concerns * Major impact to several existing residential homes * Impacts to agricultural property * Impacts to agricultural property * Impacts to existing golf course * Impacts to existing golf course * Potential cultural resources in the area resources in the area * At least two locations where impacts to Waters of the US Water Wells Water Wells Impacts to 12kV Overhead Power & Cabinets * Impacts to one residential home property * Impacts to agricultural property * Impacts to existing golf course * Potential cultural resources in the area * At least one location where impacts to Waters of the US occur Waters of the US occur * Impacts to State Land * May Impact Existing Water Wells Impacts to 12kV Overhead Power & Cabinets * Impacts to one residential property * Impacts to agricultural property * Impacts to existing golf course * Potential cultural resources in the area * At least one location where impacts to Waters of the US occur * Significant impact to	Major Utility Impacts	*		*	· -	*	,	
Water Wells Major impact to several existing residential homes Impacts to agricultural property Impacts to existing golf course Potential cultural resources in the area resources in the area where impacts to waters of the US Water Wells			Cas regulators	*	•	*	· ·	
* Impacts to 12kV Overhead Power & Cabinets Potential Environmental Concerns * Major impact to several existing residential homes * Impacts to agricultural property * Impacts to agricultural property * Impacts to existing golf course * Potential cultural resources in the area resources in the area * At least two locations where impacts to waters of the US * Impacts to 12kV Overhead Power & Cabinets * Impact to one residential home property * Impacts to agricultural property * Impacts to agricultural property * Impacts to existing golf course * Potential cultural resources in the area * At least one location where impacts to Waters of the US occur * Waters of the US * Impact to State Land * Impacts to 12kV Overhead Power & Cabinets * Impacts to agricultural property * Impacts to existing golf course * Potential cultural resources in the area * At least one location where impacts to Waters of the US occur * Significant impact to				Ť	, ,	·	-	
Potential Environmental Concerns * Major impact to several existing residential home shippoperty * Impacts to agricultural property * Impacts to existing golf course * Potential cultural resources in the area * At least two locations where impacts to waters of the US * Major impact to sevisting limit home several existing property * Impacts to agricultural property * Impacts to existing golf course * Potential cultural resources in the area * At least one location where impacts to waters of the US occur where impacts to * Waters of the US occur Waters of the US occur by waters of the US occur waters of the US occur by waters of the US occur waters of the US occur by waters of the US occur waters of the US occur by waters of t				*	Impacts to 12kV	*	Impacts to 12kV	
Potential Environmental Concerns * Major impact to several existing residential homes * Impacts to agricultural property * Impacts to agricultural property * Impacts to existing golf course * Potential cultural resources in the area * At least one location where impacts to waters of the US * Waters of the US * Impacts to one residential home property * Impacts to agricultural property * Impacts to existing golf course * Potential cultural resources in the area * At least one location where impacts to * Significant impact to * State Land					•		•	
several existing residential homes Impacts to agricultural property Impacts to existing golf course Potential cultural resources in the area At least two locations where impacts to Waters of the US Impacts to agricultural property Impacts to agricultural property Impacts to existing golf course Impacts to existing golf course Potential cultural resources in the area At least one location Waters of the US occur State Land Property Impacts to existing golf course Potential cultural resources in the area where impacts to Waters of the US occur State Land					Cabinets		Cabinets	
several existing residential homes Impacts to agricultural property Impacts to existing golf course Potential cultural resources in the area At least two locations where impacts to Waters of the US Impacts to agricultural property Impacts to agricultural property Impacts to existing golf course Impacts to existing golf course Potential cultural resources in the area At least one location Waters of the US occur State Land Property Impacts to existing golf course Potential cultural resources in the area where impacts to Waters of the US occur State Land	Potential Environmental Concerns	*	Major impact to	*	Impact to one residential	*	Impacts to agricultural	
residential homes Impacts to agricultural property Impacts to existing golf Course Potential cultural resources in the area resources in the area At least one location where impacts to Waters of the US Waters of the US Impacts to agricultural property Potential cultural resources in the area where impacts to Waters of the US occur State Land								
 Impacts to agricultural property Impacts to existing golf Impacts to existing golf course Potential cultural resources in the area resources in the area At least two locations where impacts to state Land 			residential homes	*	Impacts to agricultural	*	Impacts to existing golf	
 Impacts to existing golf course Potential cultural resources in the area where impacts to where im		*	Impacts to agricultural					
 Impacts to existing golf course Potential cultural resources in the area where impacts to where im			property	*	Impacts to existing golf	*	Potential cultural	
❖ Potential cultural resources in the area resources in the area where impacts to where impacts to ❖ At least two locations where impacts to where impacts to ❖ Significant impact to Waters of the US ❖ Impact to State Land		*	Impacts to existing				resources in the area	
resources in the area At least one location Waters of the US occur Waters of the US The second of the US occur Waters of the US The second of the US occur Waters of the US The second of the US occur Waters of the US The second of the US occur Waters of the US occur State Land			golf course	*	Potential cultural	*	At least one location	
At least two locations where impacts to where impacts to Waters of the US where impacts to Waters of the US occur Significant impact to State Land * Significant impact to State Land		*	-		resources in the area		where impacts to	
where impacts to Waters of the US occur State Land Waters of the US			resources in the area	*	At least one location		Waters of the US occur	
Waters of the US ❖ Impact to State Land		*	At least two locations		where impacts to	*	Significant impact to	
			where impacts to		Waters of the US occur		State Land	
occur			Waters of the US	*	Impact to State Land			
			occur					
❖ Impact to State Land		*	Impact to State Land					
Preliminary Project Cost \$232,200,000 \$62,700,000 \$61,700,000	Preliminary Project Cost	\$23	2,200,000	\$62	,700,000	\$61	,700,000	



6.0 RECOMMENDATIONS FOR FURTHER STUDY

Alternative 3 is recommended for further study. The Alternative 3 Conceptual Plans are included in **Appendix B** of this report. The following are issues/factors that contribute to the decision to recommend Alternative 3:

- Alternative 3 proposes to design the Hiller Road Realignment so that it is a continuous and does not require a reduction in design speed in order to accommodate a left turn or right turn movement for vehicles that travel between Mobile Road/Smith-Enke Road and Hiller Road.
- This alternative proposes an alignment that divides the State Land property east of Green Road. The proposed roadway alignment would create a potential development corridor along the Hiller Road Realignment that would increase the economic potential for the City of Maricopa.
- Minimal impact to residential/commercial properties is anticipated with this alternative.
- This alternative would widen the existing Smith-Enke Road bridge over the Santa Cruz Wash instead of constructing a entirely new bridge along the Hiller Road alignment. A new bridge along the Hiller Road alignment would increase project costs significantly and require more impact to "Waters of the US".

Alternatives 1 and 2 are not recommended for further study. The following are issues/factors that contribute to the decision to not recommend these alternatives.

- Alternative 1 was eliminated from further study due to the significant impact to numerous residential properties impacted by the proposed alignment.
- Alternative 2 was eliminated from further study due to the significant impact to the existing residential property located along the Green Road alignment.

Although Alternative 3 was recommended for further study, Alternative 1 may be a viable alternative for future consideration if the Gila River Indian Community wants to be a willing partner with the City of Maricopa in the ownership and construction of this alternative. The City of Maricopa does not have any jurisdiction to obtain right-of-way from the Gila River



Indian Community; therefore, Alternative 1 was evaluated entirely outside of the Gila River Indian Community boundary.



APPENDIX A: Survey Report

SURVEY REPORT

For

The South Boundary of the Gila River Indian Reservation Revised March 21, 2008

The purpose of this report is to detail the history and true position of the South Boundary of the Gila River Indian Reservation (GRIR) in Township 4 South, Range 2 East, and Township 4 South, Range 3 East, of Gila and Salt River Meridian, within the Town of Maricopa, Arizona. The location of this boundary has been the source of uncertainty in the past several years, resulting in the perception that a strip of "no-man's land", up to several hundred feet wide, exists along the common boundary between the Town of Maricopa and the GRIR. The intent of this report is to clarify the record title associated with this strip of land.

The history of the GRIR Boundary begins with the original U.S. Bureau of Land Management (BLM) surveys of the section lines within the subject townships. These surveys were conducted by G.P and W.F. Ingalls in 1868, and the Final Plats were officially filed by the BLM on December 2, 1870. Field notes from the surveys indicate that the monuments set were hewn mesquite posts. The Final Plats show the "Addition to the P. and M.I. Res. Ex. Ord. 15 NOV. 1883", which established what is now the GRIR. The South Boundary of the GRIR, as established in 1883, is the South line of Sections 7 through 12, which is also the North line of Sections 13 through 18, in both townships. Copies of these Plats are attached to this report, and are numbered "1518" and "1521".

Resurveys of portions of the exterior boundaries of the subject townships, and the South Boundary of the GRIR, were conducted by Guy P. Harrington and Robert A. Palmer in 1910-1912. These resurveys were independent of the original surveys by Ingalls, and resulted in the setting of a second set of monuments to the North of the original monuments. Field notes from the surveys indicate that the monuments set were brass caps on iron posts. The sections north of the resurveyed South Boundary of the GRIR were subsequently resurveyed and subdivided. Final Plats of these surveys were officially filed by the BLM on December 9, 1921. Copies of these Plats are attached to this report, and are numbered "1517" and "1520".

Portions of the exterior township boundaries and interior section lines of the subject townships, south of the GRIR, were resurveyed by Francis E. Joy in 1933 and Roger F. Wilson in 1936. These resurveys were dependent upon and compatible with the original surveys by Ingalls in 1868. Final Plats of these surveys were officially filed by the BLM on September 3, 1937 and February 29, 1940. Copies of these Plats are attached to this report, and are numbered "1516" and "1519". Clearly defined on these Plats is a gap between the South line of Sections 7 through 12 as surveyed by Harrington and Palmer in 1910-1921, and the North line of Sections 13 through 17 as surveyed by Ingalls in 1868. This gap is the so-called "no-man's land" previously referred to in this report.

In March through August 1985, the BLM conducted a Dependent Resurvey of the South line of Sections 7 through 12 surveyed by Harrington and Palmer in 1910-1921, and the North line of Sections 13 through 18 surveyed by Ingalls in 1868. The purpose of the Survey was to determine the true position of the South Boundary of the GRIR as originally established by

Ingalls in 1868, along the North line of Sections 13 through 18 of the subject townships. Field notes of the 1985 survey indicate that the Independent Resurveys by Harrington and Farmer in 1910-1912 were erroneous. Therefore the gap (of "no-man's land") between the South Boundary of Sections 7 through 12, and the South boundary of the GRIR was determined by the BLM to belong to the GRIR.

The 1985 survey was executed by Stephen Malloy and Paul Reeves. In each township, Tracts 37 through 42 were created within the above mentioned gaps. The survey clearly indicates the status of Tracts 37 through 42 as being within the GRIR, with the South Boundary of the GRIR being the South line of Tracts 37 through 42 in each township. The field notes are attached to this report, and are numbered Book 5224 and Book 5225. Final Plats of these surveys were officially filed by the BLM on April 30, 1986. Copies of these Plats are attached to this report, and are numbered "1515-A" and "1519-A".

The Town of Maricopa was informed recently by one of the property owners along the route that a law suit is on-going regarding the location of the GRIR Boundary. The Town was told that the case is being handled by the Arizona Attorney General's Office, as case number CIC 00-15345. AZTEC contacted the AG's office and was informed that CIC 00-15345 was a consumer complaint filed with the Consumer Protection and Advocacy Section, Consumer Information & Complaints Unit of the AG's office. It had nothing to do with a lawsuit, but was a complaint filed by a consumer against a business in 2000. The AG's office recommended that AZTEC contact the Transportation Section if further information was required.

AZTEC contacted the Transportation Section and was informed that there is one case, Case No. CV 05-2048-PHX-JAT, related to the GRIR, however this is not a case involving the location of the GRIR boundary. A copy of the decision is attached to this report. This case involves access to a landlocked parcel in Section 16, Township 4 South, and Range 4 East. The Transportation Section referred AZTEC to Perkins and Coie, a law firm that was associated with the case, to see whether additional information is available. The lawyer handling the case for Perkins and Coie is on sabbatical until May 2008, and is unavailable to provide any further information at this time. Should there be an on-going case, the resulting court decision could have an impact on the location of the GRIR boundary.



BOOK 5224 ORIGINAL

1

United States DEPARTMENT OF THE INTERIOR BURRAU OF LAND MANAGEMENT

FIELD NOTES

		OF !	THE					<u>:</u>
		DEPENDENT 1	RESURVEY	•				·
	OF A PORT!	ON OF THE	SUBDIVISIO	NAL LI	ŒS			
	· ·	ANI	D .	• • • •	•		•	
	SURVEY (OF TRACT NO	s. 37 THR)U(3H 42				
	,	IN		•	•			
	TOWNS	IIP 4 SOUTH	, RANGE 2	EAST.				
					•			
	, ,	:		,				
:	•	 	······					•
		**		. •				
05 17- 04	1	Issaw				•	Mori	dian,
	la and Salt R	rver	 		-:		_ PELI	aron,
In the State of	Arizona					·····	.,	<u></u>
• • • • • • • • • • • • • • • • • • • •	• • • •	• •		••		••		
	•	EXECUT	KD BY			•		
•		•	•		:	•	•	
Paul L. Reeves,	Cadastral Su	rveyor				:		
	***		• • •		•			
		•		}				
								•
Under special inst			,	100E -		Marcala 1	D	1985
- 878 184 7			7.					2.2
and supplemental s								
	, which p	rovided for	the surv	eys inc	luded u	nder Gro	up Num	ber
663 and as	signment inst	ructions da	ted <u>Marc</u>	h 18		, 19	85	
						·		
						•		
	Survey come	enced Marc	h 20		1985			
e de la companya de l	Survey comp				1985			

BOOK 5224

2

INDEX DLAGRAM

		TOWNSHIP	4 80UH	RANGE 2 E	ST	
		•		;		
Τ	· · · · · · · · · · · · · · · · · · ·					
	6	5	4	. 3	2	1
						•
					· · ·	
						•
"	7	8	9	10	11	12
.			**	15		10
19	<i>,</i>	18 8	17.	6	13 5	4
.					•	
1	L8	17	16	15	14	13
<u> </u>			,			
!	· ·					
						1 22
:	19	20	21	22	23 	24
1	• • •		. • • • • • • •			
 						
					00	0.5
,	30	29 	28	27	26	25
	• •					
Ţ						
;	31	32	. 33	34	35	. 36
,)T	32	35	34	35	, Ju.

T 4 S, R 2 E, Gila and Salt River Mer., Arizona

CHAINS

The following field notes are those of the dependent resurvey of a portion of the subdivisional lines and the survey of Tract Nos. 37 through 42, Township 4 South, Range 2 East, Gila and Salt River Meridian, Arizona.

The purpose of this survey is to determine the true position of the south boundary of the Gila River Indian Reservation along the north boundary of sections 13, 14, 15, 16, 17 and 18 as originally established by Wilfred F. Ingalls in 1868, as shown on the plat approved April 16, 1869.

Portions of the south, north and west boundaries and a portion of the subdivisional lines were surveyed by Wilfred F. Ingalls, in 1868. The east boundary was surveyed by George P. Ingalls, in 1868. Portions of the north and west boundaries were surveyed and portions of the north and west boundaries and the erroneous south boundary of the GRIR were independently resurveyed by Guy P. Harrington and Robert A. Farmer, in 1910-12. Sections north of the erroneous GRIR were independently resurveyed and most were subdivided by Robert A. Farmer, in 1912. Portions of the south boundary were resurveyed and the remainder surveyed by Sidney E. Blout, in 1922. A portion of the subdivisional lines was surveyed and others were resurveyed by Francis E. Joy, in 1933. A portion of the subdivisional lines were resurveyed by Roger F. Wilson, in 1936.

Scott Engineering ©o. did considerable surveying in this township in 1941, and the record of that survey was used as applicable for the restoration of the 1868 survey. A copy of this survey plat was found in the records maintained by Michael P. Wier, Registered Land Surveyor No. 07247, AZ.

The survey was executed in accordance with the specifications as set forth in the Manual of Surveying Instructions, 1973, and the Special Instructions dated Märch 18, 1985, and the Supplemental Instructions dated June 21, 1985, for Group No. 663, Arizona.

Preliminary to the resurvey, the necessary lines of the original survey of 1868 and the independent resurvey of 1910-12, and the 1933 and 1936 surveys, were retraced and search was made for all corners and other calls of the record. Identified corners were either remonumented in their original position or the evidence was buried in place; lost corners were restored at positions which best reflect their original location based on past records. The retracement data were thoroughly verified and only the true line field notes are given herein.

The directions of all lines were determined by observations on a U.S.C.& G.S. triangulation network, and confirmed by altitude observations on the sun, and refer to the true meridian. Distances and angles were measured with a Zeiss Total Station instrument.

The geographic position of the southeast corner of Tract 42, T 4 S, R 2 E, as determined from a tie made

T 4 S, R 2 E, Gila and Salt River Mer., Arizona

to U.S.C. & G.S. triangulation station "ENID 1936", located in the NW quarter of section 18, T 4 S, R 2 E,

is as follows:

Latitude: 33°05'13.16" N Longitude: 112°05'59.21" W

The mean magnetic declination is 14° E.

Dependent Resurvey, of the True South Boundary of the Gila River Indian Reservation, T 4 S, R 2 E, Gila and Salt River Mer., Arizona

Reestablishment of the survey executed by Wilfred F. Ingalls and George P. Ingalls, in 1868, and partially resurveyed by Francis E. Joy, U.S. Cadastral Engineer, in 1933

Beginning at the cor. of secs. 13 and 18 only, originally established by Ingalls in 1868 and reestablished by Roger F. Wilson in 1936, and now also standing for AP 8, Tract 42, and AP 6, Tract 37, Tps. 4 S, Rs. 2 and 3 E, monumented with an iron post, 1 in. diam., projecting 12 ins. above ground, with brass cap mkd. as described in the field notes of the concurrent resurvey in T. 4 S, R 3 E, executed under this same group.

S 89°36' W, bet. sec. 13 and Tract 42.

Over rolling land, through cultivated fields.

39.27

Point for the 4 sec. cor. of sec. 13 only, originally established by Ingalls in 1868 as the 4 sec. cor. of secs. 12 and 13, at proportionate dist.; there is no evidence of the original cor. This cor. now also stands for AP 7, Tract 42, T 4 S, R 2 E,

Set an aluminum post, 36 ins. long, 3 in. diam., 84 ins. in the ground, and directly atop, set a stainless steel post, 28 ins. long, 25 ins. diam., 26 ins. in the ground, with brass cap, both caps mkd.

T4S R2E AP7 TR42 GRIR 4 S13 1985

Deposit a magnet in a $1 \times 1 \times 25/8$ in. white colored plastic case beneath the stainless steel post.

Set a fiberglass marker near the cor, ..

78.54

Point for the cor. of secs. 13 and 14 only, originally established by Ingalls in 1868 as the cor. of secs. 11, 12, 13 and 14, at double proportionate position using Scott Engineering records for longitudinal control and the original 1868 record for latitudinal control; there is no evidence of the original cor. This cor. now also stands for AP 8, Tract 41 and AP 6, Tract 42, T 4 S, R 2 E.

Dependent Resurvey, of the True S Bdy. of the GRIR, T 4 S, R 2 E, Gila and Salt River Mer., Arizona

CHAINS

Set an aluminum post, 36 ins. long, & in. diam., 84 ins. in the ground, and directly atop, set a stainless steel post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap; both caps mkd.

T4S R2E GRIR AP8 AP6 TR41 TR42 S14 S13 1985

Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the stainless steel post.

Set a fiberglass marker near the cor.

S 89°51' W, bet. sec. 14 and Tract 41.

Over cultivated fields.

39,49

Point for the 1 sec. cor. of sec. 14 only, originally eatablished by Ingalls in 1868 as the 1 sec. cor. of secs. 11 and 14, at single proportionate position using the Scott Engineering record; there is no evidence of the original cor. This cor. now also stands for AP 7, Tract 41, T 4 S, R 2 E.

Set an aluminum post, 36 ins. long, & in. diam., 84 ins. in the ground, and directly atop, set a stainless steel post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground with brass cap; both caps mkd.

T4S R2E AF7 TR41 GRIR 1 S14 1985

Deposit a magnet in a $1 \times 1 \times 25/8$ in. white colored plastic case beneath the stainless steel post.

Set a fiberglass marker near the cor.

81.01

Point for the cor. of secs. 14 and 15 only, originally eatablished by Ingalls in 1868 as the cor. of secs. 10, 11, 14 and 15, at record bearing and distance as shown by the Scott Engineering record from the 1910-12 cor. of secs. 10 and 11; there is no evidence of the original 1868 cor. This cor. now also stands for AP 8, Tract 40 and AP 6, Tract 41, T 4 S, R 2 E.

Set an aluminum post, 36 ins. long, & in. diam., 26 ins. in the ground, with magnetized cap mkd.

T4S R2E GRIR AP8 AP6 TR40 TR41 S15 | S14 1985 Dependent Resurvey, of the True S Bdy. of the GRIR, T 4 S, R 2 E, Gila and Salt River Mer., Arizona

CHAINS from which A well head, bears N 70° E, 9.62 chs. dist. A well head, bears S 524° E, 2.06 chs. dist. From this point, a cor. established by Raymond L. Jones, Registered Land Surveyor, No. 5713, AZ, and which has no relation to other found original monuments, bears \$ 40°23° E, 45 lks. dist., monumented with an iron rebar, 1/2 in. diam., projecting 5 ins. above ground, with an aluminum cap mkd. E15 and a tag nkd. LS5713. From this same point, the cor. of secs. 22, 23, 26 and 27, originally established by Ingalls in 1868 and perpetuated by Wilson in 1936, bears S 0°05' W, 160.49 chs. dist., monumented with an iron post, 2 ins. diam., 3 ins. below the ground, and an open end pipe, 12 ins. diam., directly above the iron post, with brass cap mkd. T4S R2E S22 | S23 827. | S26 from which. A well head, bears N 57% E, 87 lks. dist. An iron rebar, 1 in. diam., 3 ins. below ground, with tag mkd. IS 5713, bears S 18 W, 2 1ks. dist. A concrete pillar, 6 ins. diam., projecting 20 ins. above ground, bears N 45% W, 70 lks. dist., with 3 in. brass tablet mkd. TR 631 1948 RESET AMS 1956. Also from this same point, the cor. of secs. 2, 3, 10 and 11, originally established by Ingalls in 1868 bears N 0°55' E, 80.28 chs. dist., monumented with the remains of an ironwood post, 2 ins. diam., 18 ins. long, laying loose on ground. I buried the post in place, 3 ins. below ground.

S 89°46' W. bet. sec. 15 and Tract 40.

Over rolling land.

39.92

Point for the 4 sec. cor. of sec. 15 only, originally established by Ingalls in 1868 as the b sec. cor. of secs. 10 and 15, positioned 1 ft. W of a N-S fence line, recorded by Scott Engineering and on line bet. the adjacent sec. cors. This cor. now also stands for AP 7, Tract 40, T 4 S, R 2 E.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 25 ins. in the ground, with brass cap mkd.

> **T4S R2E** AP7 TR40 GRIR 1 S15 1985

CHAINS

Deposit a magnet in a 1 x 1 x 2 5/8 in. White colored plastic case beneath the stainless steel post.

Set a fiberglass marker near the cor.

79.94

Point for the cor. of secs. 15 and 16 only, originally established by Ingalls in 1868 as the cor. of secs. 9, 10, 15 and 16, at proportionate dist. longitudinally using Scott Engineering records bet. the adjacent & sec. cors. and latitudinal position using broken bdy. proportionate position using Scott Engineering records bet. the & sec. cor. of secs. 9 and 16, and the cor. of secs. 10, 11, 14 and 15. This cor. now also stands for AP 6, Tract 39 and AP 6, Tract 40, T 4 S, R 2 E.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap mkd.

T4S RZE GRIR AP6 AP6 TR39 TR40 S16 S15 1985

Deposit a magnet in a 1 \times 1 \times 2 5/8 in. white colored plastic case beneath the stainless steel post.

Set a fiberglass marker near the cor.

From this point a cor., established by Raymond L. Jones, Registered Land Surveyor, No. 5713, and which has no relation to other found original monuments, bears N 31°37° E, 21 lks. dist., monumented with an iron rebar, ½ in. diam., projecting 3 ins. above ground, with aluminum cap mkd. W15 and a tag mkd. IS5713.

From this same point, the 4 sec. cor. of secs. 3 and 4, originally established by Ingalls in 1868 monumented with the remains of an ironwood post, 24 ins. long, 4 ins. diam., bears N 0°47'E, 119.36 ch. dist., laying loose on the ground, mkd. with illegible scribe marks. I bury the post in place, 3 ins. below ground, from which the 1910-12 4 sec. cor. of secs. 3 and 4

An iron post, 1 in. diam., filled with cement, firmly set 12 ins. below ground, bears N $24\frac{1}{2}$ E, 11.33 chs. dist.

S 89°45' W, bet. sec. 16 and Tract 39.

Over rolling land, through scattered crecsote and ironwood.

38,37

The 14 sec. cor. of sec. 16 only, originally established by Ingalls in 1868 as the 14 sec. cor. of secs. 9 and 16, remommented by Scott Engineering, in 1941, with an open end pipe, 1 in. diam., firmly set. projecting 10 ins. above ground. I accepted this cor. as a careful and faithful perpetuation of the original cor. This cor. now also stands for AP 5, Tract 39, T 4 S, R 2 E.

CHAINS	
	. The star warm' which the
	At the cor. point
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
	T4S R2E
1	AP5
'	GRIR
	½ S16
	1985
	Deposit the pipe alongside the stainless steel post.
	Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the stainless steel post.
	Set a fiberglass marker near the cor.
	N 89°56' W, beginning new measurement.
	Over nearly level land, through scattered creosote and ironwood.
41.68	The cor. of secs. 16 and 17 only, originally established by Ingalls in 1868 as the cor. of secs. 8, 9, 16 and 17, monumented with a wood post, 2 x 4 x 5 ins.
	above ground. This cor. now also stands for AP 6, Tract 38 and AP 4, Tract 39, T 4 S, R 2 E.
	At the core point
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
·	T4S R2E
٠.	GRIR
· .•	AP6 AP4 TR39 TR39
	S17 S16
	1985
	Deposit the wood post alongside the stainless steel
	post.
	Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the stainless steel post.
· .	Set a fiberglass marker near the cor.
	S 88°42' W, bet. sec. 17 and Tract 38.
•	Over nearly level land, through scattered crecsote and ironwood.
39.38	The 4 sec. cor. of sec. 17 only, originally established by Ingalls in 1868 as the 4 sec. cor. of secs. 8 and 17, and perpetuated by Francis E. Joy, in 1933, monumented with an iron post, 1 in. diam., projecting 8 ins. above ground, with brass cap mkd.
;	- The same of the
	ኳ S17 1933

			=
	CHAINS		
		Add marks to brass cap to read	
		T4S R2E	
		AP5 TR38	
		GRIR L C17	
		1985	
		1933	
		This cor. now also stands for AP 5, Tract 38, T 4 S,	
		R 2 E.	
		Set a fiberglass marker near the cor.	
-		N 83°33' W, beginning new measurement.	
		Over nearly level land, through scattered creosote and	
	**	ironwood.	
	41.86	The cor. of secs. 17 and 18 only, originally estab-	
	41.00	lished by Ingalis in 1868 as the cor. of secs. 7, 8, 17	
		and 18, and perpetuated by Francis E. Joy in 1933,	
		monumented with an iron post, 2 ins. diam., firmly set,	
		projecting 4 ins. above ground, with brass cap mkd.	
		S18 S17	
		T4S R2E	
1.0		1933	
:		Add marks to brass cap to read	
		The ment to be the to see	
i			
		GRIR AP6 /AP4	
		TR37 /TR38	
		818 S17	
		T4S R2E	
		1985 1933	
		1770	
		This cor. now also stands for AP 6, Tract 37 and AP 4,	
		Tract 38, T 4 S, R 2 E.	
		Set a steel fence post near the cor.	
		G 05°001 W 3-44 10 and Munch 27	
		S 85°20' W, bet. sec. 18 and Tract 37.	
		Over nearly level land, through scattered erecects and	
		ironwood.	
	41.57	The k sec. cor. of sec. 18 only, originally established	
	-67.57	by Ingalls in 1868 as the 4 sec. cor. of secs. 7 and	
		18, and perpetuated by Francis E. Joy in 1933,	
		monumented with an iron post, 1 in. diam., projecting 8	
		ins. above ground, with brass cap mkd.	
-			
١		⅓ s18	
		1933	
	eri, be	Add marks to brass cap to read	
		sam mario do azendo cap do zona	
ı			

		
	CHAINS	
1		1
		T4S R2E
		AP5 TR37
1		GRIR
		½ S18
- 1		1985
Į		1933
- 1	1	
		This cor. now also stands for AP 5, Tract 37, T 4 S, R 2 E.
- 1	• •	Set a steel fence post near the cor.
ı		per a sceer reine foar near me cor.
- 1		
i		N 88°57' W, beginning new measurement.
- 1		m oo or my beginning the measurement.
ł		Over nearly level land, through scattered creosote and
		palo verde.
- 1	29.85	The state of the s
- 1	29.60	The cor. of sec. 18 only, on the West boundary of the
		Tp. originally established by Francis E. Joy in 1933,
Į	. :	monumented with an iron post, 2 ins. diam., projecting
- 1		6 ins. above ground, with brass cap mkd.
-1	•	
- 1		the control of the second of the control of the second of the control of the cont
1	•	. S18
- 1		R2E
- 1		174S
- [1933
		Add marks to brass cap to read
		. T4S AP4
- [TR37
-		S13 GRIR
	-	T S18
. [-	RIE RZE
1		T4S
		1985
Ł		1933
1		
1		from which
1		
1		A palo verde, 8 ins. diam., bears S 52% E,
1		188 1ks. dist., mkd. T4S R2E S18 Rf.
1		
		This cor. now also stands for AP 4, Tract 37, T 4 6,
1		R2E.
1		Many July 2 marked 2 12 to warm a second
1		Cor. is located 1 lk. West of a N and S fence.
T	· · · · 4	From this point, U.S.C.& G.S. triangulation station
ıl.		"ENID 1936", bears S 4 49 58" E, 33.791 chs. dist.,
1		monumented with a drill hole in rock outcropping.
1	- 1	Point was verified by ties to reference monuments.
1	1	
1	•	· · · · · · · · · · · · · · · · · · ·
	- 1	
		Dependent Resurvey of the Erroneous S Bdy. of the GRIR,
		T 4 S, R 2 E, Gila and Salt River Meridian, Arizona
4		December 1 de la companya del companya de la companya del companya de la companya
	-	Reestablishment of the survey executed by
1		Robert A. Farmer, Topographer and Guy P. Harrington,
1		Cadastral Engineer, in 1910-12
1		

	CHAINS	
ł	-	From the cor. of secs. 7 and 12, on the E bdy. of Tp.,
	1	and AP 1, Tract 42 and AP 5, Tract 37, herinbefore
		described in the field notes of the dependent resurvey of a portion of the subdivisional lines and the survey
		of Tract Nos. 37 through 42, T 4 S, R 3 E, surveyed
		concurrently under this same group.
	 - !	N 89°56' W, bet. sec. 12 and Tract 42.
i		Over nearly level land, along old E and W fence line.
	20:025	The E 1/16 sec. cor. of sec. 12 only, established by R.
1	20.025	A. Farmer in 1910-12, and which now also stands for
-		AP 2. Tract 42, monumented with an iron post, 1 in.
-		diam., firmly set 10 ins. below ground, with brass cap
- 1		nkd.
-[:	**************************************
١		NO 1
١		1/16 s12 GRIR
-		1912
-		area.
		At the cor. point
1		"
-		Set a stainless steel post, 28 ins. long, 2½ ins. diam.,
1		24 ins. in the ground, with brass cap mkd.
1		T45 R2E
		GRIR
1		E 1/16 S12
1		AP2
ŀ		TR42
1		GRIR
١		1985
- [ment the manifes of the transport honouth the
1		Deposit the remains of the iron post beneath the
1	,	stainless steel post.
I		Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored
ŀ		plastic case beneath the stainless steel post.
		Set a fiberglass marker near the cor.
	1	N 89°56' W, beginning new measurement.
	• •	Over nearly level land, along an old E and W fence line.
-	20.03	The 1 sec. cor. of sec. 12 only, established by R. A.
1		Farmer in 1910-12; and which now also stands for AP 3,
ŀ		Tract 43, monumented with the remains of an Iron post,
		1 in. diam., filled with cement, firmly set 24 ins.
I		below ground.
1	1 121	At the cor. point
1		
		Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
		MAC DAM
1	ļ	T4S R2E
1	1	GRIR 1 S12
		AP3
1		TR42
	-	GRIR
1	1	1985
1		

	T 4 S, R 2 E, Gila and Salt River Mer., Arizona
CHAINS	
	Deposit the remains of the iron post alongside the
	stainless steel post.
	Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the stainless steel post.
	Set a fiberglass marker near the cor.
	N 89°54' W, beginning new measurement.
	Over nearly level land, along an old E and W fence line,
20.05	The W 1/16 sec. cor. of sec. 12 only, established by R. A. Farmer in 1910-12, and which now also stands for AP 4, Tract 42, monumented with the remains of an iron post, 1 in. diam., 24 ins. below ground.
ļ	At the cor. point
·	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
,	T4S R2E
	GRIR
	W 1/16 S12 AP4
	TR42 GRIR
	1985
	Deposit the remains of the iron post beneath the stainless steel post.
	Deposit a magnet in a $1 \times 1 \times 2$ 5/8 in. white colored plastic case beneath the stainless steel post.
	Set a fiberglass marker near the cor.
	N 89°56' W. beginning new measurement.
	Over nearly level land, along an old E and W fence line.
20,02	Point for the cor. secs. 11 and 12 only, established by R. A. Farmer in 1910-12, which now also stands for
	: AP 5, Tract 42 and AP 1, Tract 41 , at proportionate
	position using a three way proportion; there is no remaining evidence of the original cor.
	Set a stainless steel post, 28 ins. long, 25 ins. diam., 24 ins. in the ground, with brass cap mkd.
	T4s R2E
	GRIR 511 512
	API AP5 TR 41 TR 42
	GRIR 1985
1 .	

1

Form 9500-10 (June 1978) (formerly 9180-7) USDI--BLM

FIELD NOTE PAPER

Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the stainless steel post.

	T	4 6,	×	. 4	E,	Glia	ann	parr	VT AGT	Life T .	wrr	zona
			_	—					V. 111			
CHAINS												

Set a fiberglass marker near the cor.

From this point, the cor. of secs. 13 and 14 only, and and also AP 6, Tract 42 and AP 8, Tract 41, bears S 43°51' W, 7.725 chs. dist., hereinbefore described.

From this same point, the S 1/16 sec. cor. of secs. 11 and 12 established by R. A. Farmer in 1910-12, bears N 0°01' E., 23.40 ch. dist., monumented with an iron post 1 in. diam., projecting 12 in. above the ground with brass cap mdk. 1/16 S 12 No 12 1912.

N 89°56' W, bet. sec. 11 and Tract 41.

Over nearly level land, along an old E and W fence line.

20.02 The E 1/16 sec. cor, of sec. 11 only, established by R. A. Farmer in 1910-12, and which now also stands for AP 2, Tract 41, monumented with an iron post, 1 in. diam., filled with cement, flush with ground, with

brass cap mkd.

NO 1 1/16 S11 GRIR 1912

At the cor. point

Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with bress cap mkd.

T4S R2E GRIR E 1/16 S11 AP2 TR41 GRIR 1985

Deposit the iron post alongside the stainless steel post.

Deposit a magnet in a $1 \times 1 \times 2$ 5/8 in, white colored plastic case beneath the stainless steel post.

Set a fiberglass marker near the cor.

N 89°56' W, beginning new measurement.

Over nearly level land, along an old E and W fence line.

20,025

The $\frac{1}{4}$ sec. cor. of sec. 11 only, established by R. A. Farmer in 1910-12, and which now also stands for AP 3, Tract 41, monumented with the remains of an iron post, 1 in. diam., filled with cement, firmly set flush with the ground.

At the cor. point

Set a stainless steel post, 28 ins. long; 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

Form 9600-10 (June 1978) (formerly 9180-7) USDI-BLM

CHAINS	
	74s R2E
	GRIR
1	½ S11
	AP3
	TR41
	GRIR .
	1985
	Deposit the iron post alongside the stainless steel
	post.
	F
	Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored
	plastic case beneath the stainless steel post.
	DIABLIC COSE DERECT! CIR SCUINCEDS SESSE POSSE
	Set a fiberglass marker near the cor.
	Sec a liberalias market terr one con-
	an and the said of the little and the said a
	N 89°52' W, beginning new measurement.
. [the property of the contract o
	Over nearly level land, along an old E and W fence line.
	1
20.01	The W 1/16 sec. cor. of sec. 11 only, established by R.
.]	A. Farmer in 1910-12, and which now also stands for
	AP 4. Tract 41. monumented with an iron post, 1 in.
	diam., firmly set, projecting 5 ins. above ground, with
* .	brass cap nkd.
	170 O
-	NO 2
	1/16_S11
	<u>GRIR</u>
	1912
	At the cor. point
	Set a stainless steel post, 28 ins. long, 2½ ins. diam.,
·	24 ins. in the ground, with brass cap mkd.
*	24 118. In the ground, with breas cap made
	TAS R2E
	GRIR
	w 1/16 s11
	AP4
4.1	TR41
1	GRIR
	1985
	Deposit the iron post alongside the stainless steel
-	post.
	Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored
	DESCRIC A RAGINE III a L A L A 2 3/6 III WILLE COLORER
	plastic case beneath the stainless steel post.
	Set a fiberglass marker near the cor.
	18 18 18 18 18 18 18 18 18 18 18 18 18 1
	N 89°57' W. beginning new measurement.
	Over nearly level land, along an old E and W fence.
20.05	The cor. of secs. 10 and 11 only, established by R. A.
20.00	Farmer in 1910-12, and which now also stands for AP 1,
	TOTAL THE TATO THE WAY MILITAL INTO CHECK STORES THE TA
	Tract 40 and AP 5, Tract 41, nonumented with the
	remains of an iron post, 1 in. diam., filled with
	cement, firmly set 6 ins. below ground.
	At the cor. point
	± .

CHAINS	
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
1	T4s R2E
1	sio sii
ł	AP1 / AP5
1	TR40 / TR41.
ľ	1985
	Deposit the iron post alongside the stainless steel post.
	Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the stainless steel post.
	Set a fiberglass marker near the cor.
	From this point, the cor. of secs. 14 and 15, only, and also AP 8, Tract 40 and AP 6, Tract 41, bears, S 46°39' W, 8:59 chs. dist., hereinbefore described.
	N 89°56' W, bet. sec. 10 and Tract 40.
	Over nearly level land, along an old E and W fence line.
19.90	The E 1/16 sec. cor. of sec. 10 cnly, established by R. A. Farmer in 1910-12, and which now also stands for AP 2, Tract 40, monumented with an iron post, 1 in. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.
•	
	NO 1 1/16 S10
	GRIR
1	1912
	Add marks to the brass cap to read
	NO 1
	T4S R2E E 1/16 S10
	GRIR
	GRIR AP2
	TR40
'	1985
,	1912
	Set a fiberglass marker near the cor.
	N 89°57° W, beginning new measurement.
	Over nearly level land, along an old E and W fence line.
20,01	The 4 sec. cor. of sec. 10 only, established by R. A. Farmer in 1910-12, and which now also stands for AP 3, Tract 40, monumented with an iron post, 1 in. diam., projecting 12 ins. above ground, with brass cap mkd.
	½ S10
	GRIR
1	1912

-			
	CHAINS		
		Add marks to brass cap to read	
		½ S10	
		T4S R2E	
		GRIR	
		GRIR AP3	
		mp4o	
		1985	
		1912	
- 1		Set a fiberglass marker near the cor.	
-1			
-		N.89°52' W, beginning new measurement.	
ı		And the state of t	
		Over nearly level land, along an old E and W fence.	
-	20:005	The W 1/16 sec. cor. of sec. 10 only, established by R.	
		A. Farmer in 1910-12, and which now also stands for	
1		AP 4, Tract 40, monumented with an iron post, 1 in.	
-		diam., firmly set, projecting 10 ins. above ground,	
- (with brass cap mkd.	
ŀ	•	16 4 4 5 5 6 7 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	
1		NO 2	
١		1/16 S10	
1	٠,	GRIR 1912	
-		1912	
-		Add marks to the brass cap to read	
		The same of the sa	
- 1	.* .	NO 2	
-		T4S R2E	
-		W 1/16 S10	
1		GRIR	
		GRUR	
1		AP4	
1		TR40 1985	
1		1912	
١			
1		Set a fiberglass marker near the cor.	
1			
1		S COOKOL M. Providenday and an arrangement	•
1		S 89°58' W, beginning new measurement.	
1		Over nearly level land, along an old E and W fence line.	
1			
	20.02	The cor. of secs. 9 and 10 only, established by R. A.	
1		Farmer in 1910-12, and which now also stands for AP 1, Tract 39, and AP 5, Tract 40, monumented with an iron	
		Tract 39, and AP 5, Tract 40, monumented with an iron	
		post, 1 in. diam., firmly set, 8 ins. below ground, and	
		in a collar of concrete, with brass cap mkd.	
		s 9 s10	
1		RZE T4S	
1		GR IR	
1	• •	1912	
1		Add marks to brass cap to read	
	•		
1			
1			
1			
1			
1			
L			

-		
	CHAINS	
		kan di kacamatan dan kacamatan di kacamatan di kacamatan di kacamatan di kacamatan di kacamatan di kacamatan d
	[s 9 s10
	1	· R2E T4S
		GR IR
		the state of the s
		AP1 AP5
		TR39 / TR40
	1	GŖIR
		.:: 1985
		1912
		Cat a filtraminar market warm the cov
	i	Set a fiberglass marker near the cor.
	ŀ	
	l .	From this point, the cor. of secs. 15 and 16 only,
		and also AP 6, Tract 39 and AP 6, Tract 40, bears
		S 44°42' W, 8.87 chs. dist., hereinbefore described.
		N ODEEL TV hat man Q and Myroot 30
		N 89°55' W. bet. sec. 9 and Tract 39.
		Fare and a contract of the co
	l	Over nearly level land, along an E and W fence.
	40.00	The k sec. cor. of sec. 9 only, established by R. A.
		Farmer in 1910-12, and which now also stands for AP 2,
	1	Tract 39, monumented with an iron post, 1 in. diam.,
		firmly set, projecting 10 ins. above ground, with brass
		cap mkd.
	•	
		1,89.
		GRIR
		1912
	'	
		Add marks to brass cap to read
		The marks to seems out to actual
		T4S R2E
į		⅓ S9
		GRIR
		GRIR
		AP2
		TR39
		1985
		1912
ł		Set a fiberglass marker near the cor.
Ť	1.	
- [
- 1		N 89°56' W, beginning new measurement.
j		N OS SO WY DESTINATED THE MEGGGTTENBRIC.
		Additional to the state of the
į		Over nearly level land, along an old E and W fence line.
	40.00	
1	40.02	The cor. of secs. 8 and 9 only, established by R. A.
. '	. 1	Farmer in 1910-12, and which now also stands for AP 1,
1	40	Tract 38 and AP 3, Tract 39, monumented with an iron
1		post, 1 in. diam., firmly set, projecting 9 ins. above
		ground, with brass cap mkd.
		58159
	. * 1	R2E T4S
1		
		GR IR
- 1	· · ·	1912
1		taran da ang akarang ataun da ang ataun da an
١	'	Add marks to brass cap to read
-		
1		
ı		
-1		la de la companya di salah di kacamatan di salah di kacamatan di salah di salah di salah di salah di salah di s
1	, i	
j		
ı		
١		
- 1		

		<u> </u>	
	CHAINS	'	
		70170	
		S 8 S 9	
	į į	R2E T4S	
		GR IR AP1 / AP3	
		1	
		TR38 / TR39	
		GRIR	
	7.	1985	
		1912	
		Carrier and the contract of th	
	1	Set a fiberglass marker near the cor.	
		with the state of the same of the same 17 control	
		From this point, the cori of secs. 16 and 17 only,	
		and also AP 4, Tract 39 and AB 6, Tract 38, bears 8 43°45' w, 9.06 chs. dist., hereinbefore described.	
		8 45 45 W, 9.00 Chs. disc., hereimerore described.	
		From this same point, a Corps of Engineers monument	
		bears S 79 02 W, 6.36 ch. dist., morumented with a	
		concrete cone, 6 ins. diam., projecting 7 ins. above	
		the ground, mkd. Corps of Engineers TTZ 1948.	
		OR drough, more souths or strangerers are at an	
į			
į		N 89°55' W. bet. sec. 8 and Tract 38.	
	\$1		
	1	Over nearly level land, along an old E and W fence line.	
	40.04	The a sec. cor. of sec. 8 only, established by R. A.	
	20,00	Farmer in 1910-12, which now also stands for AP 2,	
. !	1	Tract 38, monumented with an iron post, 1 in. diam.,	
		firmly set, projecting 6 ins. above ground, with brass	
		cap mkd.	
		\ s 8	
	•	GRIR	
		1912	
-			
		Add marks to brass cap to read	
Ì		mia vam	
	;	T4S R2E	
1		4 58	
ı	·	GRIR	
1		GRIR AP2	
i		TR38	
Ì		1985	
		1912	
		4,474,44	
		Set a fiberglass marker near the cor.	
1			
Į			
- [N 89°59' W, beginning new measurement.	
j			
-		Over nearly level land, along an old E and W fence line.	
-			
	39,99	The cor. of secs. 7 and 8 only, established by R. A.	
1		Farmer in 1910-12, which now also stands for AP 1,	
-		Farmer in 1910-12, which now also stands for AP 1, Tract 37 and AP 3, Tract 38, monumented with an iron	
- 1		post, 1 in. diam., firmly set, projecting 5 ins. above	
1		ground, with brass cap mkd.	
		s.7 s.8	
		R2E T4S	
.		GR IR	
		1912	
1		*****	
ļ		Add marks to brass cap to read	
1	*	1	
ı			
Į			

_		
	CHAINS	
		S 7 S 8 RZE T4S GR IR API AP3 TR37 TR38 GRIR 1985 1912 Set a fiberglass marker near the cor. This cor. is located 187 lks. E of a tract road and gas line, bears NE and SW. From this point, the cor. of secs. 17 and 18 only, and also AP 6, Tract 37 and AP 4, Tract 38, bears S 68°43' W, 7.73 chs, dist., hereinbefore described.
		S 89'58' W, bet, sec. 7 and Tract 37.
	•	Over nearly level land, through scattered creosote, palo verde, ironwood and cacti.
	40.04	The 4 sec. cor. of sec. 7 only, established by R. A. Farmer in 1910-12, and which now also stands for AP 2, Tract 37, monumented with an iron post, 1 in. diam., firmly set, projecting 12 ins. above ground, with brass
	•• •• •	cap nkd.
	•	GRIR 1912
	•	Add marks to brass cap to read
		T4S R2E \$\frac{1}{4}\ \text{S7}\ \text{GRIR} \\ \text{GRIR} \\ \text{AP2} \\ \text{TR37}
		1985 1912
	•	Set a fiberglass marker near the cor.
		Cor. is located S, 4 lks. dist., of remains of a fence, extending E and W.
		West, beginning new measurement.
		Over nearly level land, through creceote, palo verde, ironwood and cacti.
	38,40	The cor. of sec. 7 only, established by R. A. Farmer in 1910-12, on the W bdy of the Tp., and which now also stands for AP 3, Tract 37, monumented with an iron post, 3 ins. diam., firmly set, projecting 10 ins. above ground, with brass cap mkd.

	1
1	•
1	R
:	lo 87
1	ic 14s
1	W RZE
l	S GRIR
	1912
İ	1312
	Remarked the brass cap to read
1	T45 S 7
	·
	R2E
1 .	S12 GRIR GRIR
1	AP3
	RIE TR37
1	l
	1912 1985
l ·	Set a fiberglass marker near the cor.
	DOC OF TENDERAL MINISTER AND PARTY P
	The cor. is located in a fence line, extending N and S.
İ	From this point, the cor. of sec. 18 only, and also
	AP 4, Tract 37, bears S 0 32' W, 5.61 chs. dist.,
•	hereinbefore described.
١.	
~	
	GENERAL DESCRIPTION
	The area in this survey is located 5 miles NW of
	Maricopa, Arizona, The elevation is about 1250 feet
	above sea level.
ļ ·	Access is by way of a paved road to the NW of Maricopa,
	then to many dirt roads.
ł	
ł	
	The soil where irrigated supports a healthy crop of
	cotton. Where it is not irrigated the clay loam soil
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde,
	cotton. Where it is not irrigated the clay loam soil
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti.
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti.
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey.
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey. The mean magnetic declination is 14° E, with a range of
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey.
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey. The mean magnetic declination is 14° E, with a range of
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey. The mean magnetic declination is 14° E, with a range of
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey. The mean magnetic declination is 14° E, with a range of
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey. The mean magnetic declination is 14° E, with a range of
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey. The mean magnetic declination is 14° E, with a range of
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey. The mean magnetic declination is 14° E, with a range of
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey. The mean magnetic declination is 14° E, with a range of
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey. The mean magnetic declination is 14° E, with a range of
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey. The mean magnetic declination is 14° E, with a range of
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey. The mean magnetic declination is 14° E, with a range of
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey. The mean magnetic declination is 14° E, with a range of
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey. The mean magnetic declination is 14° E, with a range of
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey. The mean magnetic declination is 14° E, with a range of 1° in local attraction.
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey. The mean magnetic declination is 14° E, with a range of 1° in local attraction.
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey. The mean magnetic declination is 14° E, with a range of 1° in local attraction.
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey. The mean magnetic declination is 14° E, with a range of 1° in local attraction.
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey. The mean magnetic declination is 14° E, with a range of 1° in local attraction.
	cotton. Where it is not irrigated the clay loam soil supports desert vegetation, creosote, palo verde, ironwood and cacti. There were no minerals of value noted on the line of survey. The mean magnetic declination is 14° E, with a range of 1° in local attraction.

BOOK 5224

27

UNITED STATES DEPARTMENT OF THE INTERIOR HUREAU OF LAND MANAGEMENT

FIELD ASSISTANTS

	<u> </u>
NAMES	CAPACITY
Donald L. Brewer	Surveying Technician
Robert J. Lyle	Surveying Technician
Mark Hansen	Surveying Aid
Rebecca Rameriz	Surveying Aid
11.1 17	
	•
	and the control of th
and the second s	

BOOK 5224

CERTIFICATE OF SURVEY

I, Paul L. Reeves, Cadastral Surveyor, HEREBY CERTIFY upon honor that, in pursuance of special instructions bearing date of the 18th day of March 1985, and supplemental special instructions dated Jume 21, 1985, I have dependently resurveyed a portion of the subdivisional lines and surveyed Tract Nos. 37 through 42, Township 4 South, Range 2 East, of the Gila and Salt River Meridian, in the State of Arizona which are represented in the foregoing field notes as having been executed by me and under my direction; and that said survey has been made in strict conformity with said special instructions, the Manual of Instructions for the Survey of the Public Lands of the United States, and in specific manner described in the foregoing field notes.

	on the second of the second	
•	APR 0 3 1986	PIP
	(Date)	(Cadastral Surveyor)
		The second and the second second second
		and the second of the second o
	. (Date)	(Cadastral Surveyor)
•	TO THE MEN TO SELECT MANAGEMENT OF THE SELECT	
		IFICATE OF APPROVAL
• .	The second second	Arizona State Office
. •	en en en en en en en en en en en en en e	Bureau of Land Management Phoenix, Arizona
• •	e de la companya de la companya de la companya de la companya de la companya de la companya de la companya de	
subd Sout	ivisional lines and the surv h, Range 2 East, Gila and Sa	e dependent resurvey of a portion of the vey of Tract Nos. 37 through 42, Township wait River Meridian, Arizona, executed by Repaying been critically examined and found

(Chief Cadastral Surveyor of Arizona)

(Date)

ORIGINAL BOOK 5225

UNITED STATES DEPAREMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FIELD NOTES

		OF THE		
•	DESI	PENDENT RESURVES		
	OF A PORTION	OF THE SUBDIVIS	SIONAL LINES	
		AND		
	SURVEY OF T	PACT NOS. 37 TE	IROUGH 42	
	•	IN		
	TOWNSHIP	4 SOUTH, RANGE	3.EAST	
•				
				:
				•
* * * *	** * * * * **		44 (4.54)	•
Of the	Gila and Salt Ri	vor .	•	Meridian,
In the State of _			 	rectutari,
02 _	-111222			
• • • • •	•		••	• •
2 •		EXECUTED BY		
			•.	
Paul L. Reeves	, Cadastral Survey	or .		
Stephen J. Mal	loy, Cadastral Sur	veyor	· · · · · · · · · · · · · · · · · · ·	
·····		· · · · · · · · · · · · · · · · · · ·		
nder special ins	tructions dated M	arch 18	1985, approved i	Warch 18, 1985
and supplemental	special instructi	ons dated and a	pproved July 18,	1985
			*:	der Group Number,
663 and as	ssignment instruct			
	Survey commence	l April 24	, 1995	
	Correct annual above		2005	

BOOK 5225 2

INDEX DIAGRAM

4 SOUTH PANCE 3 EAST

6	5	4.	3	2	1
7	8		io	- 11	. 12
23	2 <u>1</u>	19 8	17 6	14 5	12 3
18	17	16	15	14	13
19	20	21.	22	23	24
30	29	28	27	26	25
31	32	33	34	35	36

T 4 S, R 3 E, Gila and Salt River Mer., Arizona

CHAINS

The following field notes are those of the dependent resurvey of a portion of the subdivisional lines and the survey of Tract Nos. 37 through 42, Township 4 South, Range 3 East, Gila and Salt River Meridian, Arizona,

The purpose of this survey is to determine the true position of the south boundary of the Gila River Indian Reservation along the north boundary of sections 13, 14, 15, 16, 17 and 18, as originally established by George P. Ingalls, in 1868, as shown on the plat approved April 16, 1869.

The exterior boundaries and subdivisional lines were surveyed by G.P. and W.F. Ingalls, in 1868. Portions of the north, east and west boundaries were independently resurveyed and the erroneous south boundary of the Gila River Indian Reservation was independently resurveyed by Guy P. Harrington and Robert A. Farmer, in 1910-12. The sections north of the erroneous Gila River Indian Reservation were independently resurveyed and subdivided by Robert A. Farmer, in 1911. The south boundary, a portion of the west boundary and portions of the subdivisional lines were dependently resurveyed and certain sections were subdivided by Roger F. Wilson, in 1936.

The survey was executed in accordance with the specifications as set forth in the Manual of Surveying Instructions, 1973, and the Special Instructions dated March 18, 1985, and the Supplemental Instructions dated July 18, 1985, for Group No. 663, Arizona.

Preliminary to the resurvey, the necessary lines of the original 1868 survey and the 1910-12 independent resurvey and the 1936 survey were retraced and search was made for all corners and other calls of the record. Identified corners were remonumented in their original positions or the evidence was buried in place; lost corners were restored and monumented at proportionate positions based on the original record. The retracement data were thoroughly verified and only the true line field notes are given herein.

The direction of all lines was determined by altitude observations on the sum and refers to the true meridian. Distances and angles were measured with a Zeiss Total Station instrument.

The geographic position of the southeast corner of section 12, as determined from a tie made to U.S.C.&G.S. triangulation station "ENID 1936", located in the NW4 of section 18, T. 4 S., R. 2 E., is as follows:

Latitude: 33°05'16.43" N Longitude: 111°59'43.76" W

The mean magnetic declination is 14° E.

Dependent Resurvey of the True South Boundary of the Gila River Indian Reservation T 4 S, R 3 E, Gila and Salt River Mer., Arizona

Reestablishment of the survey executed by G.P. and W.F. Ingalls, U.S. Deputy Surveyors, in 1868

CHAINS

From this point, the cor. of secs. 13, 14, 23 and 24, originally established by Ingalls in 1868, perpetuated by Sheldon K. Baker, Civil Engineer, in 1923, and further accepted by the County Highway Department, as recorded in book 4-3B, and further utilized by U.S. Department of the Interior, Bureau of Reclamation, in 1946 and 1985, bears S 0°10° E, 80.78 chs. dist., incommented with the remains of an iron post, 1 indiam., firmly set, 8 ins. below the surface; this cor. is accepted as a careful and faithful perpetuation of the original cor.

From this same point, the 1 sec. cor. of secs. 11 and 12, originally established by Ingalls in 1868, and superseded by R.A. Farmer in 1910-12, bears N 0°19' E, 40.39 chs. dist., monumented with a hewn mesquite post, 4 ins. long, 2 ins. sq., with axe marks on end and side; I buried the hewn post in place 6 ins. below the ground; from which the N 1/16 sec. cor. of secs. 11 and 12, established by R.A. Farmer in 1910-12, bears N 5°48' E, 23.57 chs. dist., hereinafter described.

The control lines were fully retraced and no evidence of the intervening cors. was found.

S 86°34' W, bet. sec. 14 and Tract 41.

Desc. over nearly level land, through cultivated fields.

40.08

Point for the 4 sec. cor. of sec. 14 only, originally established by Ingalls in 1868 as the 4 sec. cor. of secs. 11 and 14, at proportionate dist.; there is no evidence of the original cor. This cor. now also stands for AP 7, Tract 41, T 4 S, R 3 E.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap mkd.

T4S R3E TR41 AP7 GRIR \$ 814 1985

Deposit a magnet in a $1 \times 1 \times 25/8$ in. White colored plastic case beneath the stainless steel post.

Set a fiberglass marker alongside the cor.

This cor. is located West, 5 lks. dist. from an irrigation canal, 9 lks. wide, extending N and S. In the course of setting this cor., I found fragments of Indian pottery along the canal around the cor. location. The original notes called for this cor. to be in a deserted Indian Village.

79.80

Dirt road, 30 1ks. wide, bears N and S.

80.16

Point for the cor. of secs. 14 and 15 only, originally established by Ingalls in 1868 as the cor. of secs. 10, 11, 14 and 15, at proportionate dist.; there is no evidence of the original cor. This cor. now also stands for AP 8, Tract 40, and AP 6, Tract 41, T 4 S, R 3 E.

Form 9600-10 (June 1978) (formerly 9180-7) USDI-BLM

ı	Set a	stainless	steel.	post.	28	ins.	long,	21/2	ins.	diam.,

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap mkd.

T4S R3E GRIR AP8 AP6 TR40 TR41 S15 | S14 1985

Deposit a magnet in a $1 \times 1 \times 2$ 5/8 in. White colored plastic case beneath the stainless steel post.

Set a fiberglass marker alongside the cor.

From this point, the original cor. of secs. 2, 3, 34 and 35, Tps. 4 and 5 S, R 3 E, perpetuated by Lynn Ames Winkler, Jr., Registered Land Surveyor, No. 11898, AZ, bears S 0°02' E, 319.47 chs. dist., mommented with a steel rebar, ½ in. diam., 3 ins. below the ground, with tag mkd. 11898, from which bearing objects mkd. by Wilson, in 1936.

- A power pole, bears N 59° E, 77 lks. dist., lines extend E and W. (Record: N 57½° E)
- A power pole, bears N 84° W, 398 lks. dist., lines extend E and W. (Record: 395 lks. dist.)
- A well head, bears N 60° W, 375 lks. dist. (Record: N 64½° W, 379 lks. dist.)

From this same point, the 1 sec. cor. of secs. 2 and 3, originally established by Ingalls in 1868 and superseded by R.A. Farmer in 1910-12, bears N 0°19' W, 119.79 chs. dist., monumented with a hewn mesquite post, 24 ins. long, 2½ ins. sq., lying loose on ground, no marks visible. I buried the post in place, 6 ins. below the ground, from which the cor. of secs. 2, 3, 10 and 11, established by R.A. Farmer in 1910-12, bears 5 6°01' E, 31.17 chs. dist., hereinafter described.

The control lines were fully retraced and no evidence of the intervening cors. was found.

N 88°21' W, bet. sec. 15 and Tract 40.

Continue over nearly level land, through cultivated fields.

Flood control canal, 175 lks. wide, 15 ft. deep, bears N and S.

Maricopa Road, asphalt surfaced, bears N 26° E and S 26° W.

Point for the ½ sec. cor. of sec. 15 only, originally established by Ingalls in 1868 as the ½ sec. cor. of secs. 10 and 15, at proportionate dist.; there is no evidence of the original cor. This cor. now also stands for AP 7, Tract 40, T 4 S, R 3 E.

1.50

28.20

40,39

CHAINS

CHAINS

Set an aluminum post, 36 ins. long, % in. diam., 64 ins. in the ground, with cap; and directly atop, set a stainless steel post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap; both caps mkd.

T4S R3E GRIR AP7 TR40 4 S15 1985

Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the stainless steel post.

Set a fiberglass marker alongside the cor.

The cor. is located in a cultivated field.

80.78

Point for the cor. of secs. 15 and 16 only, originally established by Ingalls in 1868 as the cor. of secs. 9, 10, 15 and 16, at proportionate dist.; there is no remaining evidence of the original cor. This cor. now also stands for AP 8, Tract 39 and AP 6, Tract 40, T 4 S, R 3 E.

set an aluminum post, 36 ins. long, % in. diam., 64 ins. in the ground, with cap; and directly atop, set a stainless steel post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap; both caps mkd.

T4S R3E GRIR AP8 AP6 TR39 TR40 S16 S15 1985

Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the spainless steel post.

Set a fiberglass marker alongside the cor.

The cor. is located in a cultivated field.

From this point, the cor. of secs. 21, 22, 27 and 28, originally established by Ingalls in 1868 and perpetuated by Wilson in 1936, bears 8 0°09° E, 162.25 chs. dist., monumented with a cement column, 4 ins. sq., 4 ins. below the surface of the ground, in a surveyors well. The cor. is located in the road intersection, asphalt surfaced, bears N, S and E.

From this same cor., the point for the cor. of secs. 3, 4, 33 and 34, Tps. 3 and 4 S, R 3 E, originally established by Ingalls in 1868 and superseded by R.A. Farmer in 1910-12, bears N 0°30' W, 162,86 chs. dist. This point was determined at proportionate dist.; there is no remaining evidence of the original cor. position. No permanent monument was established.

From the point for the 1868 cor. of secs. 3, 4, 33 and 34, Tps. 3 and 4 S, R 3 E, the cor. of Tps. 3 and 4 S, Rs. 2 and 3 E, originally established by Ingalls in

CHAINS

1868 and superseded by R.A. Farmer in 1910-12, bears \$ 88.57 W, 243.38 chs. dist., monumented with the remains of a hewn post and post hole, 3 ins. sq., no marks visible on fragmentary piece, from which an iron post set by Farmer in 1910-12

An iron post, 3 ins. diam., firmly set, projecting 8 ins. above ground, bears N 43°22° E 11.32 chs., dist., with brass cap mkd. T3S T4S R2E R3E S1 S6 S31 S36 EM 1118 1119 and a cross in the center.

Also from the point for the 1868 cor. of secs. 3, 4, 33 and 34, Tps. 3 and 4 S, R 3 E, the 4 sec. cor. of secs. 1 and 36, Tps. 3 and 4 S; R 3 E, originally established by Ingalls in 1868 and superseded by R.A. Farmer in 1910-12, bears N 88°57' E, 200.97 chs. dist., monumented with the remains of a hewn post, 18 ins. long, 2 ins. sq., lying loose on top of ground, with axe marks on edge, which I buried in place, from which and Indian allotment monument

An iron post, 2 ins. diam., firmly set, projecting 16 ins. above ground, bears S 72°42' E, 3.01 chs., dist., with brass cap mkd. INDIAN AILOTMENT & S36 S1 REF 50 FT.

The control lines were fully retraced and no evidence of the intervening cors. was found.

S 88°49' W, bet. sec. 16 and Tract 39.

Continue over rolling land, through irrigated fields.

40.03

Point for the 4 sec. cor. of sec. 16 only, originally established by Ingalls in 1868 as the 4 sec. cor. of secs. 9 and 16, at proportionate dist.; there is no evidence of the original cor. This cor. now also stands for AP 7, Tract 39, T 4 S, R 3 E.

Set a stainless steel post, 28 ins. long, 2^{l_1} ins. diam., 26 ins. in the ground, with brass cap mkd.

T4S R3E GRIR AP7 TR39 4 S16 1985

Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the stainless steel post.

Set a fiberglass marker alongside the cor.

From this cor., a point established by Pinal County Engineer, bears 8 7°55' E, 1.64 chs. dist., monumented with an open end pipe, 1½ ins. diam., firmly set, projecting 12 ins. above ground. This monument was set using improper controls and is not utilized in the course of this survey.

Continue over rolling land, along south edge of Maricopa Sanitary Land Fill.

CHAINS

54.10

Leave Maricopa Samitary Land Fill.

80:06

Point for the cor. of secs. 16 and 17 only, originally established by Ingalls in 1868 as the cor. of secs. 8, 9, 16 and 17, at proportionate dist.; there is no evidence of the original cor. This cor. now also stands for AP 8, Tract 38 and AP 6, Tract 39, T 4 S, R 3 E.

Set an aluminum post, 36 ins. long, 3 in. diam., 64 ins. in the ground, with a cap; and directly atop, set a stainless steel post, 28 ins. long, 22 ins. diam., 26 ins. in the ground, with brass cap; both caps mkd.

T4S R3E GRIR TR38 / TR39 AP8 AP6 S17 | S18 1985

Deposit a magnet in a $1 \times 1 \times 2$ 5/8 in. White colored plastic case beneath the stainless steel post.

Set a fiberglass marker alongside the cor.

The cor. is located on the E edge of a cultivated field, edge bears N and S.

From this point, the cor. of secs. 16, 17, 20 and 21, originally established by Ingalls in 1868 and perpetuated by Wilson in 1936, bears S 0°35' W, 81.34 chs. dist., monumented with an iron post,. 2 ins. diam., firmly set, projecting 6 ins. above ground, with brass cap mkd.

T4S R3E <u>817 | S16</u> <u>520 | S21</u> 1936

From this same cor., the point for the cor. of secs. 4, 5, 32 and 33, Tps. 3 and 4 S, R.3 E, originally established by Ingalls in 1868 and superseded by R.A. Farmer in 1910-12, bears N 0°14' W, 163.05 chs. dist. This point was determined at proportionate dist., there is no remaining evidence of the original cor. position. No permanent monument established.

From the point for the 1868 cor. of secs. 4, 5, 32 and 33, Tps. 3 and 4 S, R 3 E, the 1868 cor. of Tps. 3 and 4 S, Rs. 2 and 3 E, bears 8 88°57' W, 162.99 chs. dist., hereinbefore described.

From the point for the 1868 cor. of secs. 4, 5, 32 and 33, Tps. 3 and 4 S, R 3 E, the 1868 4 sec. cor. of secs. 1 and 36, Tps. 3 and 4 S, R 3 E, bears N 88°57' E, 281,36 chs. dist., hereinbefore described.

The control lines were fully retraced and no evidence of the intervening cors. was found.

\$ 89°52' W. bet. sec. 17 and Tract 38.

Continue over rolling land, through irrigated fields.

	CHAINS	
	40.29	Point for a sec. cor. of sec. 17 only, originally established by Ingalls in 1868 as the a sec. cor. of
		secs. 8 and 17, at proportionate dist., there is no evidence of the original cor. This cor. now also stands for AP 7, Tract 38, T 4 S, R 3 E.
		Set an aluminum post, 36 ins. long, 3 in. diam., 64 ins. in the ground, with cap, and directly atop, set a stainless steel post, 28 ins. long, 22 ins. diam., 26
		ins. in the ground, with brass cap; both caps mkd.
1		T45' R3E
1		GRIR
1		AP7 TR38 - 4 S17
1		1985
ì		1505
		Deposit a magnet in a $1 \times 1 \times 2$ 5/8 in. white colored plastic case beneath the stainless steel post.
		Set a fiberglass marker alongside the cor.
		Continue over rolling land, through irrigated fields.
	80.58	Point for the cor. of secs. 17 and 18, only, originally established by Ingalls in 1868 and perpetuated by
ľ		Wilson in 1936 as the cor. of secs. 7, 8, 17 and 18, at
ı	•	proportionate dist.; there is no evidence of the
1		original cor. This cor. now also stands for AP 8,
ĺ		Tract 37 and AP 6, Tract 38, T 4 S, R 3 E.
ı		Set an aluminum post, 36 ins. long, 3 in. diam., 64 ins.
I		in the ground, with cap; and directly atop, set a
I		stainless steel rost, 28 ins. long, 22 ins. dlam.,
ļ		26 ins. in the ground, with brass cap; both caps mkd.
İ	Array E	T4s R3E
Į		GRIR
l		AP8 AP6
Į		TR37 / TR38 S18 S17
I		1985
ı		
		Deposit a magnet in a 1 x 1 x 2 $5/8$ in. white colored plastic case beneath the stainless steel post.
l		Set a fiberglass marker alongside the cor.
		From this point, the 1936 S 1/16 sec. cor. of secs. 17 and 18, bears S 0°14' W, 60.20 chs. dist., monumented with an iron post, 1 in. diam., firmly set, flush in the the ground, with brass cap mkd.
l		s 1/16

This cor. is located in a fence cor.; fences extend S and E.

818 | 8 MIR | 1936

From this same cor., the 1 sec. cor. of secs. 7 and 8, originally established by Ingalls in 1868 and superseded by R.A. Farmer in 1910-12, bears N 0°48' E, 40.13 chs. dist., monumented with the remains of an original hewn post, 12 ins. long, 3 ins. sq., projecting 3 ins. above ground, no marks visible;

		The state of the s	=
	CHAINS		
		buried the original post in place 6 ins. below the surface of the ground. From which the cor. of secs. 7 and 8 only, established by R.A. Farmer in 1910-12, bears S 5°47' E, 35.39 chs. dist., hereinafter described.	
		The control lines were fully retraced and no evidence of the intervening cors. was found.	
		N 89°57' W, bet. sec. 18 and Tract 37.	
		Continue over rolling land, through irrigated fields.	
	40.20	Point for the 4 sec. cor. of sec. 18 only, orginally established by Ingalls in 1868 and reestablished by Wilson in 1936, as the 4 sec. cor. of secs. 7 and 18, at proportionate dist.; there is no evidence of the original cor. This cor. now also stands for AP 7, Tract 37, T 4 S, R 3 E.	
		Set an aluminum post, 36 ins. long, 3 in. diam., 64 ins. in the ground, with cap; and directly atop, set a stainless steel post, 28 ins. long, 24 ins. diam., 26 ins. in the ground, with brass cap; both caps mkd.	
		T4s R3E	
i	* .	GRIR	
		AP7 TR37 4 S18	
		1985	
		Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the stainless steel post.	
		Set a fiberglass marker alongside the cor.	
		Continue over rolling land, through irrigated fields.	
	60.30	Leave irrigated field, enter desert edge, bears N and S.	
	82.17	The cor. of secs. 13 and 18, only, originally established by Ingalls in 1868 and reestablished by Wilson in 1936 as the cor. of secs. 7, 12, 13 and 18, Tps. 4 S, Rs. 2 and 3 E, monumented with an iron post, 2 ins. diam., firmly set, projecting 12 ins. above	
		ground, with brass cap mkd.	
		T4S	
		R2E R3E S12 S 7	ŀ
		S13 S18	
		1936	
		I remarked the brass cap to read	
		GRIR	
		AP8 AP6 TR42 TR37	
		S13 S18	
	İ	R2E R3E T4S	
		1985	
		1936	
	1		1
			1

CHAINS	This cor. now also stands for AP 6, Tract 37, T 4 S, R 3 E, and AP 8, Tract 42, T 4 S, R 2 E.
	R 3 E, and AP 8, Tract 42, T 4 S, R 2 E.

Set a fiberglass marker alongside the cor.

Dependent Resurvey of the Erroneous S Edy. of the GRIR T 4 S, R 3 E, Gila and Salt River Mer., Arizona.

> Reestablishment of the survey executed by Robert A. Farmer, Topographer, and Guy P. Harrington, Cadastral Engineer, in 1910-12

From the cor. of secs. 7 and 12, only, Tps. 4 S, Rs. 3 and 4 E, established by R.A. Farmer in 1910-12 heretofore described in the field notes of the dependent resurvey of a portion of the subdivisional lines of T 4 S, R 4 E, surveyed concurrently under this same group.

N 89°32' W, bet. sec. 12, T 4 S, R 3 E, and sec. 18, T 4 S, R 4 E.

Desc. over W slope, through rolling, broken land.

1.30 Power line, extends N and S.

2.20 The cor. of secs. 13 and 18, only, Tps. 4 S,
Rs. 3 and 4 E, and also AP 1, Tract 42, heretofore
described in the field notes of the dependent resurvey
of a portion of the subdivisional lines of T 4 S, R 4 E,
surveyed concurrently under this same group.

West, beginning new measurement. between sec. 12 and Tract 42.

Continue over rolling land, along S edge of a dirt road, 25 lks. wide, bears N 89° W, and E.

17.80 Point for the E 1/16 sec. cor. of sec. 12 only, established by R.A. Farmer in 1910-12, at proportionate dist.; there is no evidence of the cor. This cor. now also stands for AP 2, Tract 42, T 4 S, R 3 E.

Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground, with brass cap mkd.

T4S R3E GRIR E 1/16 S12 GRIR TR42 AP2 1985

Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the stainless steel post.

This cor. is located on S edge of dirt road, 25 lks. wide, bears E and W.

Continue over rolling land, along E edge of dirt road.

		T 4 S, R 3 E, Gila and Salt River Mer., Arizona
1	CHAINS	
	37.80	The 1 sec. cor. of sec. 12 only, established by R.A. Farmer in 1910-12, monumented with the remains of an iron post, filled with cement, 1 in. diam., firmly set 8 ins. below the surface of the ground. This cor. now also stands for AP 3, Tract 42, T 4 S, R 3 E.
		At the cor. point
		Set a stainless steel post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap mkd.
		T4s R3E GRIR ½ S12 GRIR TR42 AP3 1985
		Deposit the remains of the iron post beneath the stainless steel post.
		Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the stainless steel post.
		Set a fiberglass marker alongside the cor.
		This cor. is located on the S edge of a dirt road, 25 lks. wide, bears E and W.
		N 89°53' W, beginning new measurement.
		Continue over rolling land, along the S edge of a dirt road, 25 lks. wide, bears E and W.
	20.02	The W 1/16 sec. cor. of sec. 12 only, established by R.A. Farmer in 1910-12, monumented with the remains of an iron post, 1 in. diam., filled with cement, firmly set 12 ins. below the ground. This cor. now also stands for AP 4, Tract 42, T 4 S, R 3 E.
	J	At the cor. point
		Set a stainless steel post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap mkd.
		T4S R3E GRIR W 1/16 S12 GRIR TR42 AP4 1985
!		Deposit the remains of the iron post beneath the stainless steel post.
	ī .	

Deposit a magnet in a 1 x 1 x 2 5/8 in. White colored plastic case beneath the stainless steel post.

Set a fiberglass marker alongside the cor.

The cor. is located on S edge of a dirt road, $25~\mathrm{lks.}$ wide, bears E and S.

Form 9600-10 (June 1978) (formerly 9120-7) USDI--BLM

٦	CHAINS		
		N 89°55' W, beginning new measurement.	
		Continue over rolling land, along S edge of a dirt road, 25 lks. wide, bears E and W.	
	20.01	Point for the cor. of secs. 11 and 12 only, established by R.A. Farmer in 1910-12, at proportionate dist.; using a three way proportion there is no evidence of the cor. This cor. now also stands for AP 1, Tract 41 and AP 5, Tract 42, T 4 S, R 3 E.	
		Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground, with brass cap mkd.	
1		T46 R3E	
	,	GRIR S11 S12 TR 41 TR 42 AP 1 AP 5 1985	
	:	Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the stainless steel post.	
		Set a fiberglass marker alongside the cor.	
		This cor. is located on the S edge of a dirt road, 25 lks. wide, bears N, E and W.	
	l	From this point, the N 1/16 sec. cor. of secs. 11 and 12, established by R.A. Farmer in 1910-12, bears N 0°02'W, 63.50 chs. dist., monumented with an iron post, 1 in. diam., firmly set, projecting 14 ins. above ground, with brass cap mkd.	
	;	N 12	
		1/16 S11 S12 1911	
		This control line was fully retraced and no evidence of the intervening cors. was found.	
		From this same point, an open end pipe, of unknown origin, 12 ins. long, ½ in. diam., projecting 1 in. above ground, bears S 34°36' W, 0.19 chs. dist.	
		Also from this same point, the cor. of secs. 13 and 14 only, and also AP 8, Tract 41 and AP 6, Tract 42, bears 8 81 53' W, 2.67 chs. dist., hereinbefore described.	
		N 89°56' W, bet. sec. 11 and Tract 41.	
		Continue over rolling land, along S edge of dirt road, 25 lks. wide, bears E and curving S.	
	2:20	Dirt road, 25 lks. wide, bears NE and S, continue along old fence, extending W.	
	20:00	The E 1/16 sec. cor. of sec. 11 only, established by R.A. Farmer in 1910-12, monumented with the remains of an iron post, 1 in. diam., filled with cement, firmly set, 6 ins. below the ground. This cor. now also stands for AP 2, Tract 41, T 4 S, R 3 E.	
	[·		

1	CHAINS		
		At the cor. point	
		Set a stainless steel post, 28 ins. long, 2½ ins. diam., 27 ins. in the ground, with brass cap mkd.	
		T4s R3E GRIR E 1/16 S11 GRIR TR41 AP2	
	•	1985 Deposit the remains of the iron post beneath the	
		stainless steel post.	
		Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the stainless steel post.	
	ş	Set a fiberglass marker alongside the cor.	
		The cor. is located under old fence, extends E and W.	
	45.	N 89°57' W, beginning new measurement.	
	••	Continue over rolling land, along old fence, extends E and W.	
	20100	The % sec. cor. of sec. 11 only, established by R.A. Farmer in 1910-12, and which now also stands for AP 3, Tract 41, T 4 S, R 3 E, monumented with an iron post, 1 in. diam., projecting 6 ins. above ground, with brass cap mkd.	
		GRIR \frac{1}{4} S11 1911	
		Add marks to brass cap to read	
		GRIR 4 S11 TR41 AP3	
		1985 1911	
		Set a fiberglass marker alongside the cor.	
	4"	This cor. is located under an old fence, extending E and W.	
		N 89°45' W, beginning new measurement.	
		Continue over rolling land, along an old fence, extending E and W.	
	19.875	The W 1/16 sec. cor. of sec. 11 only, established by R.A. Farmer in 1910-12, and which now also stands for AF 4, Tract 41, T 4 S, R 3 E, monumented with an iron post, 1 in. diam., projecting 6 ins. above ground, with brass cap mkd.	
	- 1		
	-		
J			٠

Form 9600-10 (June 1978) (formerly 9180-7) USDI--BLM

		T 4 S, R 3 E, Gila and Salt River Mer., Arizona
	CHAINS	
		GRIR 1/16 N 2 S11 1911
		Add marks to cap to read
		GRIR W 1/16 N 2 S11
		GRIR
		TR41 AP4 1985
		1911
ĺ		Set a fiberglass marker alongside the cor.
	"	
		S 89°36' W, beginning new measurement.
		Continue over rolling land, along the N edge of a dirt road, 15 lks. wide, bears E and W.
	20.02	Point for the cor. of secs. 10 and 11 only, established by R.A. Farmer in 1910-12, at proportionate dist.;
		using a three way proportion; there is no evidence of the cor. This cor. now also stands for AP 1, Tract 40 and AP 5, Tract 41, T 4 S, R 3 E.
	•	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap mkd.
		T4S R3E
		GRIR
		S10 S11 AP1 / AP5
		TR40 / TR41 GRIR
		1985
		Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the stainless steel post.
Ì		Set a fiberglass marker alongside the cor.
		The cor. is located on the E side of a flood control canal.
	•	From this point, the cor. of secs. 14 and 15 only, and also AP 8, Tract 40 and AP 6, Tract 41, bears S 28°12' W, 5.85 chs. dist., hereinbefore described.
		From this same point, the cor. of secs. 2, 3, 10 and 11, established by R.A. Farmer in 1910-12, bears N 0°06' W, 83.60 chs. dist., monumented with an iron post, 1 in. diam., firmly set, projecting 2 ins. above ground, with brass cap mkd.
		S 3 S 2 R3E T4S S10 S11 1911
		This control line was fully retraced and no evidence of the intervening cors. was found.

	CHAINS		
		N 89°51' W, bet. sec. 10 and Tract 40.	
		Continue over rolling lend.	
	1.10	Canal, 115 ft. wide, 15 ft. deep, extends N and S.	
	20.02	The E 1/16 sec. cor. of sec. 10 only, established by R.A. Farmer in 1910-12, and which now also stands for AP 2, Tract 40, T 4 S, R 3 E., monumented with an iron post, 1 in. diam., firmly set, projecting 10 ins. above the ground, with brass cap mkd.	
		GRIR .1/16 N 1 S10 1911	
		Add marks to cap to read	
		GRIR E 1/16 N 1 S10 AF2 TR40 GRIR 1985 1911	
		Set a fiberglass marker alongside the cor.	
		g 89°59' W, beginning new measurement.	
		Continue over rolling land, along the N edge of a dirt road, 15 lks. wide, bears E and W.	
	8.30	Maricopa Road, 50 1ks wide, bears N 26° E and S 26° W.	
	20.00	The 1/2 sec. cor. of sec. 10 only, established by R.A. Farmer in 1910-12, and which now also stands for AP 3, Tract 40, T 4 S, R 3 E, monumented with the remains of an iron post, 1 in. diam., filled with cement, firmly set 6 ins. below the ground.	
		At the cor. point	
		Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 27 ins. in the ground, with brass cap mkd.	
		TAS R3E GRIR ½ S10 AP3 TR40 GRIR 1985	
		Deposit the remains of the iron post beneath the	
• .		beposit a magnet in a 1 x 1 x 2 5/8 in. White colored	
		plastic case beneath the stainless steel post. Set a fiberglass marker alongside the cor.	
		This cor. is located on the N side of a dirt road, 25	
		1ks, wide, bears E and W.	
	L .		1

	CHAINS	
		N 89°59' W, beginning new measurement.
	20.00	The W 1/16 sec. cor. of sec. 10 only, established by R.A. Farmer in 1910-12, and which now also stands for AP 4, Tract 40, T 4 S, R 3 E, monumented with the remains of an iron post, 1 in. diam., filled with cement, firmly set 6 ins. below the surface.
		At the cor. point
	,	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
ı		T4S R3E
1		GRIR W 1/16 S10
		W 1/10 S10 AP4 TR40
		GRIR
١		1985
		Deposit the remains of the iron post beneath the stainless steel post.
		Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the stainless steel post.
		Set a fiberglass marker alongside the cor.
		The cor. is located on the N side of a dirt road, 25 lks. wide, bears E and W.
		West, beginning new measurement.
	20.00	The cor. of secs. 9 and 10 only, established by R.A. Farmer in 1910-12, and which now also stands for AP 5, Tract 40; T 4 5, R 3 E, monumented with an iron post, 1 in. diam., firmly set, projecting 3 ins. above ground, with brass cap mkd.
		GRUR
-		S 9 S 10
1	•	<u>T4S R3E</u> 1911
		Add marks to brass cap to now read
		GRIR
1		S 9 S10
		T4S R3E AP1 / AP5
.		TR39 / TR40
		1985 1911
-		1351
		Set a fiberglass marker alongside the cor.
		This cor. is located at the end of an old fence, extending westerly.
		From this point, the cor. of secs. 15 and 16 only, and also AP 8, Tract 39 and AP 6, Tract 40, bears 5 50°07' W, 4.58 chs. dist., hereinbefore described.

 		-
CHAINS .		
	g 89°59' W, bet. sec. 9 and Tract 39.	
	Continue over rolling land, along an old fence, extending westerly.	
20.01	The E 1/16 sec. cor. of sec. 9 only, established by R.A. Farmer in 1910-12, and which now also stands for AP 2, Tract 39, T 4 S, R 3 E, monumented with the remains of an iron post, 1 in. diam., filled with cement, firmly set, flush with the surface, with brass cap mkd.	
	GRIR E 1/16 NO 1 S 9 1911	
	At the cor. point	
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 27 ins. in the ground, with brass cap mkd.	
	T4S RM GRIR E 1/16 S 9	
	AP2 TR39 GRIR 1985	
	Deposit the remains of the iron post beneath the stainless steel post.	
	Deposit a magnet in a $1 \times 1 \times 2$ 5/8 in. White colored plastic case beneath the stainless steel post.	
	Set a fiberglass marker alongside the cor.	
	N 89°57! W, beginning new measurement.	
	Continue over rolling land, along an old fence, extending E and W.	
20,01	The 4 sec. cor. of sec. 9 only, established by R.A. Farmer in 1910-12, and which now also stands for AP 3, Tract 39, T 4 S, R 3 E, monumented with the remains of an iron post, 1 in, diam., filled with cement, 6 ins.	
	below the surface.	
	At the cor. point	
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.	
	T4S R3E GRIR 4 S 9	
	AP3 TR39 GRIR	
	1985	
	Deposit the remains of the iron post beneath the stainless steel post.	
	Deposit a magnet in a 1 x 1 x 2 5/8 in. White colored plastic case beneath the stainless steel post-	

CHAINS	Set a fiberglass marker alongside the cor.
	s 89°59' W, beginning new measurement.
	Continue over rolling land, along an old fence, extending E and W.
20.01	The W 1/16 sec. cor. of sec. 9 only, established by R.A. Farmer in 1910-12, and which now also stands for AP 4, Tract 39, T 4 S, R 3 E, monumented with an iron post, 1 in. diam., firmly set, flush with the ground, with brass cap mkd.
:.	GRIR 1/16 NO 2 S9 1911
., .	At the cor. point
	Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
	T4S R3E
	Deposit the remains of the iron post beneath the stainless steel post.
	Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the stainless steel post.
	Set a fiberglass marker alongside the cor.
	N 89°57' W, beginning new measurement.
	Continue over rolling land, along an old fence, extending E and W.
20.00	The cor. of secs. 8 and 9 only, established by R.A. Farmer in 1910-12, and which now also stands for AP 1, Tract 38, and AP 5, Tract 39, T 4 S, R 3 E, monumented with the remains of an iron post., 1 in. diam., 12 ins. below the ground, no brass cap, an open end pipe, of unknown origin, 10 ins. long, 1 in. diam., projecting 3 ins. above the ground, is atop the iron post,
	At the cor. point
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with breas cap mkd. T4S R3E GRIR S 8 S 9 AP1 / AP5 TR38 / TR39
	GRIR 1985
	Deposit the remains of the iron post and the open end pipe beneath the stainless steel post.
i. je	

	T
CHAINS	
	Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the stainless steel post.
	Set a fiberglass marker alongside the cor.
	From this point, the cor. of secs. 16 and 17 only, and also AP 8, Tract 38 and AP 6, Tract 39, bears \$ 37°16° W, 5.84 chs. dist., hereinbefore described.
	N 89°58' W, bet. sec. 8 and Tract 38
	Continue over rolling land, along an old fence, extending E and W.
20.00	Point for the E 1/16 sec. cor. of sec. 8 only, established by R.A. Farmer in 1910-12, at proportionate dist.; there is no evidence of the cor. This cor. now also stands for AP 2, Tract 38, T 4 S, R 3 E,
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap mkd.
	T4S R3E. GRIR E 1/16 S 8 AP2 TR38
	GRIR , 1985
	Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the stainless steel post.
	Set a fiberglass marker alongside the cor.
	Continue over rolling land, bet. fences extending E and W and a dirt road, 15 lks. wide, bears E and W.
40.00	The 4 sec. cor. of sec. 8 only, established by R.A. Farmer in 1910-12, and which now also stands for AP 3, Tract 38, T 4 S, R 3 E, monumented with the remains of an iron post, 1 in. diam., filled with cement, firmly set 6 ins. below the ground.
	At the cor. point
,	Set a stainless steel post, 28 ins. long, 24 ins. diam., 24 ins. in the ground, with brass cap mkd.
	T4S R3E
	GRIR
1	1 188
1	AP3 TR38
	GRIR 1985
	Deposit the remains of the iron post beneath the stainless steel post.
	Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the stainless steel post.
	Set a fiberglass marker alongside the cor.

Dependent Resurvey of the Erroneous S Edy. of the GRIR T 4 S, R 3 E, Gila and Salt River Mer., Arizona

CHAINS	
	N 89°59' W, beginning new measurement.
	Continue over rolling land, bet. a fence to the N, extending E and W, and a dirt road to the S, bearing E and W.
19.98	The W 1/16 sec. cor. of sec. 8 only, established by R.A. Farmer in 1910-12, and which now also stands for AP 4, Tract 38, T 4 S, R 3 E, monumented with the remains of an iron post, 1 in. diam., filled with cement, firmly set, 38 ins. below the ground.
	At the cor. point
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap mkd.
	T4S R3E
	GRIR W 1/16 S 8
	AP4 TR38
	GRIR 1985
•	Deposit the remains of the iron post beneath the stainless steel post.
	Deposit a magnet in a $1 \times 1 \times 2 5/8$ in. white colored plastic case beneath the stainless steel post.
	Set a fiberglass marker alongside the cor.
	N 89°58' W, beginning new measurement.
	Continue over rolling land, bet. a fence to the N, extending E and W and a dirt road to the S, 15 lks. wide, bearing E and W.
20.00	The cor. of secs. 7 and 8, established by R.A. Farmer in 1910-12; and which now also stands for AP 1, Tract 37; and AP 5, Tract 38, T 4 S, R 3 E, monumented with the remains of an iron post. 1 in. diam., filled with cement, firmly set 2 ins. below the ground.
	At the cor. point
•	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap mkd.
	T4s R3E
	GRIR S7 S8
	S 7 8 8 AP1 / AP5
	TR37 / TR38
	GRIR 1985
	Deposit the remains of the iron post beneath the stainless steel post.
	Deposit a magnet in a $1 \times 1 \times 2$ 5/8 in. white colored plastic case beneath the stainless steel post.
	Set a fiberglass marker alongside the cor.

Dependent Resurvey of the Erroneous S Edy. of the GRIR T 4 S, R 3 E, Gila and Salt River Mer., Arizona

_	CHAINS		
	·	From this point, the cor. of secs. 17 and 18 only, and also AP 8, Tract 37 and AP 6, Tract 38, bears \$ 40°04' W; 6.42 chs. dist., hereinbefore described.	
		N 89°59' W, bet. sec. 7 and Tract 37.	
		Continue over rolling land, bet. a fence to the N, extending E and WSW, and a dirt road, to the S, 15 lks. wide, bearing E and W.	
	1.90	Intersect an old fence and a newer fence, extending W and ENE. respectively.	
	19,99	The E 1/16 sec. cor. of sec. 7 only, established by R.A. Farmer in 1910-12, and which now also stands for AP 2, Tract 37, T 4 S, R 3 E, monumented with the remains of an iron post, 1 in. diam., filled with cement, firmly set 12 ins. below the ground.	
		At the cor. point	
	•	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.	
		T4S R3E	
į		GRIR E 1/16 S 7	
		AP2 TR37	
		GRIR 1985	
	,	Deposit the remains of the iron post beneath the stainless steel post.	
		Deposit a magnet in a 1 x 1 x 2 $5/8$ in. White colored plastic case beneath the stainless steel post.	
		Set a fiberglass marker alongside the cor.	
-		N 89°55' W, beginning new measurement.	
		Continue over rolling land, along an old fence line, extending E and W.	
	19.98	The 1 sec. cor. of sec. 7 only, established by R.A. Farmer in 1910-12, and which now also stands for AP 3, Tract 37, T 4 S, R 3 E, monumented with the remains of an iron post, 1 in. diam., filled with cement, firmly set 30 ins. below the ground.	
		At the cor. point	
		Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.	
		T4S R3E	
		GRIR ½ S 7 AP3	
		TR37 GRIR	

Form 9600-10 (June 1978) (formerly 9180-7) USDI-BLM

10.5

The Mar

3. 1. 2. 3h 1. 1. 1.

AND THE

· 24 - 44 3

* **

me s.418?

GRIR 1985 Dependent Resurvey of the Erroneous S Bdy. of the GRIR T'4 S, R 3 E, Gila and Salt River Mer., Arizona

CHAINS	Deposit the remains of the iron post beneath the stainless steel post.
	Deposit a magnet in a $1 \times 1 \times 25/8$ in. white colored plastic case beneath the stainless steel post.
	Set a fiberglass marker alongside the cor.
:	N 89°59' W; beginning new measurement.
	Continue over rolling land, along an old fence, extending E and W.
19.99	The W 1/16 sec. cor. of sec. 7 only, established by R.A. Farmer in 1910-12, and which now also stands for AP 4, Tract 37, T 4 S, R 3 E, monumented with the remains of an iron post, 1 in. diam., filled with coment, firmly set 18 ins. below the ground.
	At the cor. point
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
	T4S R3E
•	GRIR
	<u>w 1/16 s 7</u>
-	AP4
1	TR37
1	GRIR 1985
1	1983
	Deposit the remains of the iron post beneath the stainless steel post.
	Deposit a magnet in a 1 x 1 x 2 5/8 in. white colored plastic case beneath the stainless steel post.
	Set a fiberglass marker alongside the cor.
	N 89°58' W, beginning new measurement.
	Continue over rolling land, along old fence extending E and W.
19.41	The cor. of secs. 7 and 12, established by R.A. Farmer in 1910-12, and which now also stands for AP 1, Tract 42, and AP 5, Tract 37, Tps. 4 8, Rs. 2 and 3 E, mornmented with the remains of an iron post, 3 ins. diam., 4 ins. below the ground.
	At the cor. point
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
	T48
	RZE GRIR RJE
ľ	S12 S 7 AP1 / AP5
,	AP1 AP5 TR42 TR37
	GRIR
ľ	1985
1	

Dependent Resurvey of the Erroneous S Bdy. of the GRIR T 4 S, R 3 E, Gila and Salt River Mer., Arizona

Deposit the remains of the iron post beneath the

stainless steel post.

CHAINS

Deposit a magnet in a 1 x 1 x 2 5/8 in. White colored plastic case beneath the stainless steel post.

Set a fiberglass marker alongside the cor.

From this point the cor. of secs. 13 and 18 only, and also AP 8, Tract 42 and AP 6, Tract 37, Tps. 4 8, Rs. 2 and 3 E, bears S 54°43' W, 8.495 chs. dist,. hereinbefore described.

GENERAL DESCRIPTION

The area in this survey is located about 2 miles N of Maricopa, Arizona. The elevation is about 1150 feet above sea level.

The access is by way of Maricopa Road to many dirt and gravel roads.

The soil is irrigated clay loam and supports a healthy crop of cotton. Where it is not irrigated it is desert.

There were no minerals of value noted on the lines of this survey.

The mean magnetic declination is 14° E, with a range of 1° in local attraction.

Form 9600-10 (June 1978) (formerly 9180-7) USDI---BLM

FIELD NOTE PAPER

BOOK 5225

26

UNITES STATES DEPARIMENT OF THE INTERIOR BURFAU OF LAND MANAGEMENT

FIELD ASSISTANTS · CAPACITY NAMES Donald L. Brewer Surveying Technician Robert J. Lyle Surveying Technician Stephania D. Griscavage Cadastral Program Assistant Gary G. Glintenkamp Surveying Aid Rebecca Rameriz Surveying Aid •

BOOK 5225

27

CERPIFICATE OF SURVEY

We, Paul L. Reeves and Stephen J. Malloy, Cadastral Surveyors, HEREBY CERTIFY upon honor that, in pursuance of special instructions bearing date of the 18th day of March 1985, and the supplemental special instructions dated July 18, 1985, we have dependently resurveyed a portion of the subdivisional lines and surveyed Tract Nos. 37 through 42, Township 4 South, Range 3 Bast, of the Gila and Salt River Meridian, in the State of Arizona which are represented in the foregoing field notes as having been executed by us and under our direction; and that said survey has been made in strict conformity with said special instructions, the Manual of Instructions for the Survey of the Public Lands of the United States, and in specific manner described in the foregoing field notes.

APR 0 3 1986	Paul L. Rem
(Date)	(Cadastral Surveyor)
	Control of the Control of the Control
APR 2 8 1986	State A Mally (Gadastre) Surveyor)
(Date)	Wadastrox Surveyor)

CERTIFICATE OF APPROVAL


Arizona State Office Bureau of Land Management Phóenix, Arizona

The foregoing field notes of the dependent resurvey of a portion of the subdivisional lines and the survey of Tract Nos. 37 through 42, Tomship 4 South, Range 3 East, Gila and Salt River Meridian, Arizona, executed by Paul L. Reeves and Stephen J. Malloy, Cadastral Surveyors, having been critically examined and found correct, are hereby approved.


APR 3 0 1986


(Date)


(Chief Cadastral Surveyor of Arizona)



The survey of Thomship No. 4. South Range No. 3. Rest of the Gits and Sait River Meridian, Arienta, CILA FILLER HOUSEN RESERVATION CILL RIVER HOUSEN CANADA RESERVATION CANADA RESERVA	- 1921 	1520	Jackson 33 - 177 35 Longham ITT - 00 - 74.	arranana Seca S	120 12-2-1051		Control of Society			ě	0. 3. East of the Mark the pield man of mined cycle capement.
See, 22. See, 23. See, 24. See		Meridian, s		2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	OFFICALLY FILED 12-2-		25 and 25		Sec. 36.		which the family of Empley and with the family of Empley and with the family of Empley and with the family of Empley and with the family of Empley and Emp
See, 75.		ila and Sall Biver RVATION.		(Seminary)		•			. Sec. 38:		The above they, of The Oile and Bill Bire. Me the strengthent in fit OENTALL 1.467. Problems 77. 10.00
See, 75.		3Bast of the G		0000 0000 0000 0000 0000 0000 0000 0000 0000			28. Sec. 27.	•	•		
C. 20. Sec. 18. Sec.				3 8 -9 5 5 2 5 6 6 -9 5 6 2 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6			*				When Surraped the Control of the Con
		onship No4 S	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7							wher of Aer	9








	1518		HED 12-2-1870				1			19577.58 Hors 3410 00	THE PARTY OF THE P			arrays thank on fit in the After Mandam
		Bosevel and Alder US Landings. Pravoit Gravia. Remier 2 1990. 1922 J. V. Stefaur.	OFFICIALLY FILED						•	Negrogate Evera of Public Land surveyed Islinoted 'Area of nasuroged Massless' India Letinoted 'Area of nasuroged Massless' Land	States	**	کارناوی کارنامی کارنامی ایران کارنامی کارنامی کارنامی کارنامی کارنامی کارنامی کارنامی کارنامی کارنامی کارنامی گلمتا تعدیل کارنامی کارنامی کارنامی کارنامی کارنامی کارنامی کارنامی کارنامی کارنامی کارنامی کارنامی کارنامی کا	The chow illy of Guarley I' is Yould, Boog I'!! East of Illie and is shirtly indiversally to be failed with of the Guards of the Surveyor Unreef or show here examined and againment. Surveyor "Surveyor "Surveyor", Illiente, 1916. Left, I' lot the Ass.
7. 16. 27. 18.	Oila and Salt Kiver Meridisa cz so so	2 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	091 188 091 091	ord. 15 No	2 040	Marie CA.	2003	3 mg 2000 7 10 C C	640	2	640 + 640	173/10 173/10 173/10 W	15rd 35 5/4 36 25 6/40 6/40 8/40 8/40 8/40 8/40 8/40 8/40 8/40 8	1668. 1868. 1868. 1968.
T. 1702 G.	Nauye 19 . A.L.ast, U	See See See See See See See See See See	%	To P and H. I. Res. Ex.	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		540 540 540	t	17.00 049 6 11	3 2	W. Watta	K. S.		State of Carmer State of State
Townshin Not. South	A TOUCH.	Marine State of th	ANNI PARTITO	Jaainon	The married Advinosity of the Section of the Sectio		7199.	1, 00 5 5 60 60 60 1 1 100 100 100 100 100 100 10	All Million Commences		of Dance	2 c t (12 5	20 20 20 20 20 20 20 20 20 20 20 20 20 2	18116.0

1517 DFFICIALLY FILED 12-9-1921 Resurvey of Township No.4. South Range No. 2. East. of the Gila and Salt River Meridian, Ariaona.
GILA RIVER INDIAN RESERVATION the survey thersof on flash this Office, wh GENTRAL LAND OFFICE | J Sec. 35. Sea 22. FO. 10 1- DE DEE. Sec. 17. Sec. 18.

THOMIY RIED 9-3-1937 4 SOUTH, RANGE Nº 2 EAST, GILA AND SALT RIVER MERIDIAN, ARIZONA. DEPENDENT AND INDEPENDENT RESURVEY AND EXTENSION SURVEY DEPARTMENT OF THE INTERIOR GENERAL LAND OFFICE Depres Colores Depres Colores Depres Depres Colores Depres Colores Depres 868 Resurveyed by S.E. Blout in 1922 R.A. Former in 1912 Surreyed AREA 163301 Acts. Independent Resur. 1,019,03 ... Dependent Resur. 2,157,52 ... Total 4,809.56 ... LINES RESIGNATED BY WHOLK SUNCTED IN GOOD AND A WILE WEEK STATES CHELLITO CONTINUED IN CONTINUED State of Claim in mod 8 TOWNSHIP Nº Long 112- 12- 14.

Book 5224 42% Þ 7 Sheet 1 of 2 Sheets 1515-A ORIGINAL The history of surveys is centained in the UNITED STATES DEPARTMENT OF THE DATENTOR BENEAU OF LAND MANABENENT This plat is strictly contermable to the species titled notes, now the nursey having been convectly excelled a been convectly excelled a been contemporate of law and the regulations of this Bersau is mare accepted. lames F. Heller Chief Cadastral Surveyor of Artizon TOWNSHIP 4 SOUTH, RANGE 2 EAST, OF THE GILA AND SALT RIVER MERIDIAN, ARIZONA For the Director Phoenix, Arizona -------Sec. 12 Officially Filed 76-37 3-13-1-6-1-6-RESERVATION Sec. 11 TRACT 42 DEPENDENT RESURVEY INDIAN Sec. 10 N. 80° 55 W. Sec. 12 TRUCT 42 41.37 Chains Sec. 13 ENLARGED DIAGRAM Sec. 9 RIVER Sec. 11 1.89 % r. 20.05 TRACT 41 Sec. 14 ENLARGED DIAGRAM *** SOULE N. 50 'X. Y. Sec. 8 BILA N. 89°57 W. Sec. 7 U.S.C.E E.S. A OW SHELT THACT 41 TRACT 40

5 6 3 2





APPENDIX B: Alternative 3 Conceptual Plans

